KANSAS

FORM: CP-3
Rev. 5-5-81

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT REPORT

Sec. 7 Twp. 26—SRge. 3 (East) **Mexiconty Butler Total Depth 3245' Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Aspen Oil Inc. Wichita, Ks. 67207 License No. Operation Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 19 81 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx, cemt. in rathole. RECEIVED STATE CORROBATION COMMISSION Wichita. Kansas RECEIVED STATE CORROBATION COMMISSION Wichita. Kansas None REVERIVED STATE CORROBATION DIVISION Wichita. Kansas	
perator's Full Name Bronco Oil Inc. Complete Address PO Box 18001, Wichita, Ks. 67207 Lease Name De Moss Well No. # 1 Location NW SW SW SW Sec. 7 Twp.26-SRge. 3 (East) Sweet) County Butler Total Depth 3245' Chandoned Oil Well Gas Well Input Well SWD Well De A X Cother well as hereafter indicated Clugging Contractor Aspen Oil Inc. Wichita, Ks. 67207 License No. Cher well as hereafter indicated Clugging Contractor Aspen Oil Inc. Wichita, Ks. 67207 License No. Cher well as hereafter indicated Clugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED COMPRENATION DIVISION Wichita, Kansas AND COMPRENATION DIVISION Wichita, Kansas COMPRENATION DIVISION Wichita, Kansas AND COMPRENATION DIVISION Wichita, Kansas Comprenation Division Wichita, Kansas Comprenation Division Comprenation Division Wichita, Kansas Comprenation Comprenation Division Wichita, Kansas Comprenation Comprenation Division Comprenation Comprenation Comprenation Comprenation Comprenation Comprenation Comprenation Comprenation Comprenation Co	API Number 15-015 - 21,823-60-00
perator's Full Name Bronco Oil Inc. Complete Address PO Box 18001, Wichita, Ks. 67207 Lease Name De Moss Well No. # 1 Location NW SW SW Sw Sec. 7 Twp.26—SRge. 3 (East) ** County Butler Total Depth 3245' Cher well as hereafter indicated Plugging Contractor Aspen Oil Inc. Wichita, Ks. 67207 License No. Departion Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 19 81 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt. pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED COMMENSION STATE CORPORATION COMMINISSION Wichita, Kansas RECEIVED COMMENSION Wichita, Kansas Composenvation DINISION Wichita, Kansas	200 Colorado Derby Bldg-
Complete Address PO Box 18001, Wichita, Ks. 67207 Case Name De Moss Well No. # 1 Cocation NW SW SW2 Sec. 7 Twp.26—SRge. 3 (East) ** County Butler Total Depth 3245' County Butler Total Depth 3245	
De Moss Well No. # 1 Ocation NW SW SW SW Sec. 7 Twp.26—SRge. 3 (East) ** County Butler Total Depth 3245' County Butler SwD Well De A X County Butler SwD Well Butler Butler SwD Well Butler	
Sec. 7 Twp. 26-SRge. 3 (East) SMARKEN COUNTY Butler Total Depth 3245' Shandoned Oil Well Gas Well Input Well SWD Well DeA X Other well as hereafter indicated Plugging Contractor Aspen Oil Inc. Wichita, Ks. 67207 Address 7701 E. Kellogg Suite 575. License No. Operation Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 19 81 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION Wichita. Kansas RECEIVED STATE CORPORATION ONINISSION Wichita. Kansas None RECEIVED STATE CORPORATION ONINISSION Wichita. Kansas	
District Butler Total Depth 3245' Subandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Aspen Oil Inc. Wichita, Ks. 67207 Address 7701 E. Kellogg Suite 575. Operation Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 19 81 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED CONSERVATION DIVISION WICHIA. Kansas CONSERVATION DIVISION WICHIA. Kansas	
Swip well as hereafter indicated Plugging Contractor Aspen Oil Inc. Michita, Ks. 67207 Address 7701 E. Kellogg Suite 575. Departion Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 19 81 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED CONSERVATION COMMISSION Wichita. Kansas Wichita. Kansas Wichita. Kansas Wichita. Kansas	
Plugging Contractor Aspen Oil Inc. Address 7701 E. Kellogg Suite 575, Wichita, Ks. 67207 Address 7701 E. Kellogg Suite 575, License No. Deparation Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 19 81 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED CHATE COMPORATION COMMISSION Services of the Component of the	County Butler Total Depth 3245'
Plugging Contractor Aspen Oil Inc. Wichita, Ks. 67207 License No. Departion Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 1981 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE COMPORATION COMMISSION STATE COMPORATION DIVISION Wichita. Kansas OMNISERVATION DIVISION Wichita. Kansas I hereby cantal the above well was plugged as herein stated.	Abandoned Oil Well Gas Well Input Well SWD Well D & AX
Departion Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 1981 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION STATE CORPORATION COMMISSION Wichita Kansas I hereby century that the above well was plugged as herein stated.	Other well as hereafter indicated
Departion Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 1981 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION STATE CORPORATION COMMISSION Wichita Kansas I hereby century that the above well was plugged as herein stated.	Plugging Contractor Aspen Oil Inc.
Operation Completed: Hour: 6:30 PM Day: 3 Month: 8 Year: 1981 Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8 - 6 8 1 ANDS CONSERVATION DIVISION Wichita. Kansas I hereby century that the above well was plugged as herein stated.	Address 7701 E. Kellogg Suite 575, License No.
Plugging Operations attended by Agent? All X Part None The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION STATE CORPORATION DIVISION Wichita. Kansas I hereby century CharCthe Dove well was plugged as herein stated.	
The above well was plugged as follows: 8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8 6 8 8 9 8 9 9 8 9 9 9 9 9 9 9 9 9 9 9	
8 5/8" sur. csg. 201' circ./cemt. Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8-0-8 Aii: Conservation Division Wichita. Kansas	
Halliburton Services pumped cement. Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8-0-8 AUG CONSERVATION DIVISION Wichita. Kansas	
Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled drill pipe to 60', spotted 20 sx. cemt. to top sur. csg. Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8-0-8 ALIG CONSERVATION DIVISION Wichita. Kansas	8 5/8" sur. csg. 201' circ./cemt.
Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8-0-8 AND CONSERVATION DIVISION Wichita. Kansas	Halliburton Services pumped cement.
Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8-0-8 AND CONSERVATION DIVISION Wichita. Kansas	Filled hole/mud, ran drill pipe 210', spotted 30 sx. cemt., pulled
Dumped 5 sx. cemt. in rathole. RECEIVED STATE CORPORATION COMMISSION 8-0-8 ANG CONSERVATION DIVISION Wichita. Kansas	
RECEIVED STATE CORPORATION COMMISSION RECEIVED STATE CORPORATION COMMISSION AND CONSERVATION DIVISION Wichita. Kansas	
STATE CORPORATION COMMING. TO STATE CORPORATION	- Jamped / Jaks Johnson
CONSERVATION DIVISION Wichita. Kansas I hereby certify that the above well was plugged as herein stated.	RECEIVED TOTALION COMMISSION
I hereby centify that the above well was plugged as herein stated.	STATE CORPORATION COMMENTS & - 6 - 8
I hereby centify that the above well was plugged as herein stated.	Wile o ic.
I hereby centify that the above well was plugged as herein stated.	CONSERVATION DIVISION What A Kansas
	I hereby cent by that the above well was plugged as herein stated.
DATE 9-17-8/ Signed: Won Thompson	DATE 9-17-8/ Signed: Non Knompson
INV. No. 9804-6	Conservation Division Agent