

KCC OIL/GAS REGULATORY OFFICE

Date 7/11/08

- (☒) New Situation
 () Response to Request
 () Follow-up

Operator license # 32198Operator Petro Santander (USA) IncAddress 6363 Woodway Drive, Ste 380 Location SE. NW, Sec 13, T 21 S, R 35 WHouston, Tx 77057Lease Christabelle Morrow Well # Scott 1-13 WSWCounty KearnyOperator phone number 713 784 8700API # 15-093-20684-0001

Reason for Investigation: _____

Complete Alternate II Cementing

Problem: 8 $\frac{3}{8}$ " 564', 5 $\frac{1}{2}$ " 4376 w/ 275sx; DV tool 2010'
with 475sx on 6-30-08. Cement did not circulate. TD-4511'

Person(s) Contacted: Top of Cement by bond log is 1016'.

Findings: _____

7-11-08 Perforate 2 holes 910'. Ren + by: per to 816.

Allred Cemented with 165sx 60/40 Per 629el and
50 sx CIA + 3% CaCl₂. Circ 50sx to pit

RECEIVED
 KANSAS CORPORATION COMMISSION

JUL 21 2008

photos taken: _____

CONSERVATION DIVISION
 WICHITA, KS

Action/Recommendations: Alternate II Cementing Complete

- () Lease Inspection
 () Complaint
 (☒) Field Report

By Ken SchlikPART II

Retain 1 copy Joint District Office
 Send one copy Conservation Division

- () RBDMS () TA program
 () KGS () T-1 database
 () District files () Courthouse

25

LEASE INSPECTION

YES

[] I.D. Sign

NONE COMMENTS

[]

· [] Tank Battery

[] ; Condition: good [] , questionable [] , overflowing []

[] Pits, tank battery

[] Fluid depth _____ ft.; approx. size _____ ft. x _____ ft.

[] Pit, injection site

[]; Fluid depth ____ ft.; approx. size ____ ft. x ____ ft.

[-] Gas venting

[]

[] Oil spill evidence

11

[] Saltwater evidence

[]; Surface flow _____; seepage _____

[] Saltwater pipelines

[] ; Seepage visible Yes/No; tested for leaks Yes/No

[] Flowing holes

11

[] Abandoned wells

[]

[] TA wells

[]; Potential poll. Prob. _____; currently producing _____

[] SWD/ER Injection well

[] Permit # _____ Pressure-actual _____ psi, Authorized _____ psi

[] SWD/ER Injection well

[]	Permit # _____	Pressure-actual _____	psi, Authorized _____	psi
[]	Permit # _____	Pressure-actual _____	psi, Authorized _____	psi

[] SWD/ER Injection well

1	]; Permit #	Pressure-actual	psi, Authorized	psi
1	]; Permit #	Pressure-actual	psi, Authorized	psi

[] SWD/ER Injection well

[]; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi

[] Monitoring records

11

[] Gauge connections

[] tubing _____; T/C annulus _____; C/SP annulus _____

[] Gauge connections

]: tubing _____; T/C annulus _____; C/SP annulus _____
]: tubing _____; T/C _____; C/SP annulus _____

[] Gauge connections

[] tubing _____; T/C annulus _____; C/SP annulus _____
[] tubing _____; T/C annulus _____; C/SP annulus _____

[] Gauge connections

[]: tubing _____; T/C annulus _____; C/SP annulus _____

Lease cleanliness: Very good _____ satisfactory _____ poor _____ very bad _____

Well number & GPS coordinates:

[illegible]