KCC OIL	/GAS	REGUL	ATORY	OFFICES
---------	------	-------	--------------	----------------

Date: <u>09/16/08</u>	District: 0	1	Case	#:		
	New S	Situation	Lease Ins	spection		
	Respo	nse to Request	Complair	nt		
	Follow	v-Up	Field Rep	port		
Operator License No: 31627	API Well N	umber: <u>15-083</u>	3-21,568-00-00			
Op Name: Whitetail Crude, Inc.	Spot: <u>NE-</u>	NW-SW-SW	Sec <u>30</u> Twp <u>21</u>	_S Rng <u>23</u> E / W		
Address 1: P.O. Box 544	1040		Feet from	N/ S Line of Section		
Address 2: N Hwy 283				E/W Line of Section		
City: Ness City			Long: <u>99.89742</u>			
State: Kansas Zip Code: 67560 -0544		: <u>Tammen</u>		Well #: 2		
Operator Phone #: (785) 798-3614	•	odgeman		n'('WFD#1-30		
Reason for Investigation:						
Witness Alt.II						
Problem:						
None cement circulated to surface			-			
Persons Contacted:						
Findings:	·····					
8-5/8" @ 216'						
TD @ 4820'						
4-1/2 @ 4680'W/225sxs		1 00/ 4	0			
Port Collar @ 1673' cemented with 200sxs-smd-1/4# flo seal-2%cc-10sxs went to pit						
•						
Action/Recommendations: F	follow Up Required	Yes No	Date: _			
Alt.II requirements have been met		- 				
THE GET VEN			К	RECEIVED ANSAS CORPORATION COMMISSION		
				050 0 0000		
SEP 1 8 2008				SEP 2 2 2008		
		÷		CONSERVATION DIVISION WICHITA, KS		
Verification Sources: KCC DOGGO City	·		 	Photos Taken:		
RBDMS KGS	TA Program					
T-I Database ✓ District Files	Courthouse	By: Micha	ael Maier			
Other:						

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>



Date: 09/16/08		_	District:	01 -	Lice	nse #: <u>31627</u>		
Op Name: 31627			Spot: NE	NE-NW-SW-SW Sec <u>30</u> Twp <u>21</u> S Rng <u>23</u> ☐ E 🕢				
				me: <u>Tammen</u>		Well #: 2		
I.D. Sign Yes	No		(S)	Gas Venting	Yes No		M	
Tank Battery Cond		ole Overflow	ing	Pits Fluid Depth:	ft; Approx. Size	e:ft. x	ft.	
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:ft	. xft.	Saltwater Pi Leaks Visible		ested for Leaks: Y	n I	
Oil Spill Evidence				Flowing Ho	les			
Abandoned Well	Potential Polls	ution Problem	Yes No	TA Wells				
Lease Cleanliness Very Good S	atisfactory	Poor Very	y Bad	Monitoring	Records		·	
SWD/ER Injection Well	Yes	No	Hodgeman 😭	Gauge Connect	ions Yes No		£	
Permit #: P	ressure – Actu	al: psi; Aut	thorized: psi			; C/SP Annulus:		
Permit #: P	ressure – Actu	al: psi; Aut	thorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus:		
Permit #: P	ressure – Actu	al: psi; Aut	thorized: psi	Tubing:		; C/SP Annulus:		
Permit #: P	ressure – Actu	al: psi; Aut	thorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus:		
API Number	Footages	Spot Location	GPS	Well #		Well Status		
15-083-21, 568-00-00	1040FSL 440FWL	NE-NW-SW-SW	38.19277-99.89	742 2	New well, Alt.II cor	mpleted		
terdiktisen var Kenastis Harde	the state of							
Att 3 - 1,2	•							
1767. 1 3 1 7 1 289 485 1	,							