KCC OIL/GAS REGULATORY OFFICES

Date: 09/16/08	District: 01		Case #:		
	New S	Situation	Lease In	rspection	
	Respo	onse to Request	Compla	int	
	Follo	w-Up	Field Re	eport	
Operator License No: 7775	API Well N	umber: <u>15-13</u>	35-24,831-00-00		
Op Name: Wilton Petroleum, Inc.	Spot: <u>SE</u> -	SE	Sec <u>28</u> Twp <u>20</u>	S Rng 21 E / W	
Address 1: P.O. Box 391			Feet from	m N/S Line of Section	
Address 2:	660		Feet from	m E/W Line of Section	
City: Canton	GPS: Lat:	38.27854	_ Long: <u>99.64168</u> _	Date: <u>9/16/08</u>	
State: Kansas Zip Code: 67428 -	Lease Nam	e: <u>Bieber</u>		Well #: <u>30</u>	
Operator Phone #: <u>(620)</u> 628-4466	County: L	less			
Reason for Investigation:					
Witness Alt.II					
Problem:					
None cement circulated to suface					
Persons Contacted:					
Findings:					
8-5/8" @ 208W/165sxs cement					
TD @ 4469'					
5-1/2" @ 4468'W/150sxs cement	and 1/1# fla a	an 20/ an 20	lava want ta nit		
Port Collar @ 1450' cement with 175sxs-	sma-1/4# 110 St	3al-2%CC-20	sxs went to pit		
`	·				
Action/Recommendations:	follow Up Required	Yes N	o 🔯 Date: _		
Alt.II requirements have been met				RECEIVED KANSAS CORPORATION COMMISSION	
DECEIVED				SEP 2 2 2008	
				OOMBEDIATION DIVISION	
L SEP 1 8 2008				CONSERVATION DIVISION WICHITA, KS	
Verification Sources: Dodge City				Photos Talzan	
RBDMS KGS	TA Program			Photos Taken:	
T-I Database ✓ District Files	Courthouse	By: Mic	hael Maier		
Other:					
				·	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>09/16/08</u>		_	District:	01	Lic	ense #: <u>7775</u>
Op Name: <u>7775</u>		Spot: SE	-SE	Sec <u>28</u> Twp <u>20</u>) S Rng 21 E W	
County: Ness Lease				me: <u>Bieber</u>		Well #: <u>30</u>
I.D. Sign Yes	No		न	Gas Venting	Yes No	
Tank Battery Condi		ole Overflow	ving o	Pits Fluid Depth:	ft; Approx. Siz	ze:ft. xft.
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:ff	t. xft.	Saltwater P Leaks Visible	<u> </u>	Tested for Leaks: Y N
Oil Spill Evidence				Flowing Ho	iles	
Abandoned Well	Potential Poll	ution Problem [Yes No M	TA Wells		
Lease Cleanliness			50	Monitoring	Records	
Very Good S	atisfactory	Poor Ver	y Bad			
SWD/ER Injection Well			Ness 🖺		tions Yes No	G/SD A
Permit #:Pi						; C/SP Annulus:; C/SP Annulus:
Permit #: Pr		•	thorized: psi thorized: psi			; C/SP Annulus:
				Tubing:; T/C Annulus:; C/SP Annulus:		
API Number	Footages	Spot Location	GPS	Well #	,	Well Status
15-135-24,831-00-00	720FSL 660FEL	SE-SE	38.27854-99.64	168 30	New well, Alt.II completed	
্রার্থার, চিন্						
Mar.	1 15/12/2				·	
Fig. 12 1						
THE STATE OF THE S						
58 - FEBURY			·			
	e _x					