

# KCC OIL/GAS REGULATORY OFFICES

Date: 08/20/08

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058  
Op Name: American Warrior  
Address 1: P.O. Box 399  
Address 2: \_\_\_\_\_  
City: Garden City  
State: Kansas Zip Code: 67846 -0399  
Operator Phone #: \_\_\_\_\_

API Well Number: 15-083-21,563-00-00  
Spot: SE-NW-SW-NE Sec 2 Twp 22 S Rng 24  E /  W  
1860 Feet from  N /  S Line of Section  
2301 Feet from  E /  W Line of Section  
GPS: Lat: 38.17007 Long: 99.92527 Date: 8/20/08  
Lease Name: Goebel Well #: 1-2  
County: Hodgeman

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @ 310W/190sxs cement  
TD @ 4760'  
5-1/2" @ 4759'W/150sxs cement  
Port Collar @ 1663' cement with 150sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

RECEIVED  
KANSAS CORPORATION COMMISSION  
**AUG 29 2008**  
CONSERVATION DIVISION  
WICHITA, KS

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt. II requirements have been met

RECEIVED  
AUG 27 2008  
KCC Dodge City

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 08/20/08

District: 01

License #: 4058

Op Name: 4058

Spot: SE-NW-SW-NE Sec 2 Twp 22 S Rng 24  E  W

County: Hodgeman

Lease Name: Goebel Well #: 1-2

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-083-21,563-00-00	1860FNL 2301FEL	SE-NW-SW-NE	38.17007-99.92527	1-2	New well, Alt. II completed