## KCC OIL/GAS REGULATORY OFFICES

Date: <u>08/25/08</u>	District: _	)1	Case #:					
	New	Situation	Lease Inspection					
·	Resp	onse to Request	Complaint					
	Follo	w-Up	Field Report					
Operator License No: 3581	API Well N	umber: <u>15-135-24,829</u>	)-00-00					
Op Name: Red Oak Energy, Inc.	Spot: <u>C-S</u>	SW-NW-SE Sec 20	Twp 17 S Rng 25 $\mathbb{E}/\sqrt{W}$					
Address 1: P.O. Box 783140			Feet from N/ S Line of Section					
Address 2:			Feet from VE / W Line of Section					
City: Wichita			00.11054 Date: 8/25/08					
State: Kansas Zip Code: 67278 -3140	Lease Nam	e: <u>Lamer Trust</u>	Well #: <u>1-20</u>					
Operator Phone #: (316) 652-7373	County: 1	less						
Reason for Investigation:								
Witness Alt.II								
Problem:								
None cement circulated to surface								
Persons Contacted:								
Findings:								
8-5/8" @ 226'W/160sxs cement								
TD @ 4510'								
4-1/2" @ 4509' W/150sxs cement	md 1/1# fla	. and 20/ an 10ava w	ant to nit					
Port Collar @ 1777' cemented with 140sxs-smd-1/4# flo seal-2%cc-10sxs went to pit								
•								
·								
Action/Recommendations: Follow	w Up Required	Yes No 5	Date:					
Alt II requirements have been met			RECEIVED					
DECEIVED			KANSAS CORPORATION COMMISSION					
10			AUG 2 9 2008					
AUG 2 7 2008			CONSERVATION DIVISION WICHITA, KS					
Verification Sources. Dodge City			Photos Taken:					
	TA Program							
	Courthouse	By: Michael Maie						
Other:			· · · · · · · · · · · · · · · · · · ·					

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: <u>08/25/08</u>		-	àDistrict	District: <u>01</u> License #: <u>3581</u>					
Op Name: 3581			Spot: <u>C</u>	Spot: <u>C-SW-NW-SE</u> Sec <u>20</u> Twp <u>17</u> S Rng <u>25</u> E					
County: Ness			Lease N	Lease Name: Lamer Trust Well #: 1-20					
I.D. Sign Yes	No		Ó	Gas V	enting _	Yes No	. 0		
Tank Battery Condi		le Overflow	ing 🔊	Pi Fluid		ft; Approx. Size	:ft. xft.		
Pits, Injection Site Fluid Depth:	_ft; Approx. S	ize:ft	. xft.		ltwater Pi	<u> </u>	ested for Leaks: Y N		
Oil Spill Evidence		· · · · · · · · · · · · · · · · · · ·		FI	owing Hol	es			
Abandoned Well	Potential Pollu	ition Problem	Yes No 50	Т	A Wells		·		
				М	onitoring :	Records			
Lease Cleanliness Very Good S	atisfactory	Poor Very	Bad	-					
SWD/ER Injection Well	Yes	No	Ness 🖸	Gaug	e Connect	ions Yes No	, '		
Permit #:Pı	ressure – Actua	al: psi; Aut	horized: psi				; C/SP Annulus:		
·····					Tubing:; T/C Annulus:; C/SP Annulus:				
Permit #: Pi					Tubing:; T/C Annulus:; C/SP Annulus:				
Permit #:Pı	ressure – Actua	al: psi; Aut	horized: psi	Tubir	ng:	; T/C Annulus:	; C/SP Annulus:		
API Number	Footages	Spot Location	GPS	· .	Well #		Well Status		
15-135-24,829-00-00	1530FSL 2310FEL	C-SW-NW-SE	38.55567-100.	11054	1-20	New well, Alt.II con	npleted		
· · · · · · · · · · · · · · · · · · ·									