KCC OIL/GAS REGULATORY OFFICES

Date: 08/20/08	District: 0	1		Case #:				
330,43133	_			Lease Inspection				
•	LJ	nse to Request	-	Complaint				
	Follov		<u> </u>	Field Report				
	II			_				
Operator License No: 4058		umber: <u>15-1</u>	· ·					
Op Name: American Warrior				Twp 19 S Rng 22 E	لنا			
Address 1: P.O. Box 399				Feet from N/S Line of S				
Address 2:				Feet from E/W Line of				
City: Garden City				73133 Date: 8/20/08				
State: <u>Kansas</u> Zip Code: <u>67846 -0399</u>				Well #: <u>1-14</u>				
Operator Phone #:	· County: N	ess						
Reason for Investigation:								
Witness Alt.II								
Problem:	· ·							
None, cement circulated to surface								
,		•						
				······································				
Persons Contacted:		· · · · · · · · · · · · · · · · · · ·						
					•			
Findings:		·						
8-5/8" @ 227W/160sxs cement								
TD @ 4354'								
5-1/2" @ 4353'W/150sxs cement Port Collar @ 1452' cement with 155sxs-smd-1/4# flo seal-2%cc-10sxs went to pit								
The second with the second with the second to the second with the picture of the second with the second with the second with the second with the picture of the second with th								
				•				
Action/Recommendations: Follow	Up Required	Yes N	0 🔊	Date:	<u>.</u>			
Alt.II requirements have been met								
I I MECEIVEM				RECEIVED KANSAS CORPORATION COMMIS	SION			
AUG 2 7 2008()				AUG 2 9 2008				
4				CONSERVATION DIVISION				
Verification Sources Dodge City				WICHITA, KS				
Verification Sources Value of the Verifi				Photos Taken:				
<u> </u>	A Program	Rv. Min	hael Maier					
	ourthouse	Dy. IVIIC	Haci Maici		3			
Other:								

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>08/20/08</u>	District	: <u>01</u>	Lice	nse #: <u>4058</u>			
Op Name: 4058	Spot: <u>E/</u>	Spot: <u>E/2-SW-SW-SW</u> Sec <u>14</u> Twp <u>19</u> S Rng <u>22</u> ☐ E ✓ W					
County: Ness	Lease Na	ease Name: Keith Well #: 1-14					
I.D. Sign Yes No	S	Gas Venting	Yes No	Ŋ			
Tank Battery Condition		Pits					
Condition: Good Questionable O	verflowing	Fluid Depth:	ft; Approx. Size	e:ft. xft.			
Pits, Injection Site		Saltwater Pi	pelines	n n			
Fluid Depth:ft; Approx. Size:	Leaks Visible: Y N Tested for Leaks: Y N						
Oil Spill Evidence		Flowing Holes					
Abandoned Well Potential Pollution Pro	blem Yes No	TA Wells	•				
		-					
		Monitoring	Records				
Lease Cleanliness Very Good Satisfactory Poor	ি Very Bad						
SWD/ER Injection Well Yes No	Ness 🖸	Gauge Connect	ions Yes No	Ŋ			
Permit #: Pressure - Actual:	psi; Authorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus:			
Permit #: Pressure – Actual:	psi; Authorized: psi			; C/SP Annulus:			
Permit #: Pressure - Actual:	psi; Authorized: psi			; C/SP Annulus:			
Permit #: Pressure - Actual:	psi; Authorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus:			
API Footages Loca		Well #		Well Status			
330FSL 15-083-24,824-00-00 350FWL E/2-SW-S	sw-sw 38.39357-99.73	3133 1-14	New well, Alt.II con	mpleted			
				·			
			4,				
				•			
- 3.2 -							