KCC OIL/GAS REGULATORY OFFICES

Date: <u>07/10/08</u>	District: _)1	•	Case	#:
	New S	Situation		Lease Insp	pection
	Respo	onse to Request		Complain	t
•	Follo	w-Up		Field Rep	ort
Operator License No: 3842	API Well N	umber: <u>15-1</u>	01-22 109-0	: 000	
Op Name: Larson Engineering, Inc. dba Larson Operating Company			•		S Rng 29 E / W
Address 1: 562 W State Rd. 4					N/\sqrt{S Line of Section}
Address 2:					E/W Line of Section
City: Olmitz					Date: <u>7/10/08</u>
State: <u>Kansas</u> Zip Code: <u>67564</u> <u>-8561</u>					Well #: 1-20
Operator Phone #: (620) 653-7368	County: 1				
Reason for Investigation:					
Witness Alt.II	· · · · · · · · · · · · · · · · · · ·			,	
Problem:					
None cement circulated to surface					
Persons Contacted:			,		
Findings:			,		
8-5/8" @ 247'W/175sxs cement					
TD @ 4667'					
5-1/2" @ 4643'W/225sxs cement	1 4 14 11 61	. 00/	00		
Port Collar @ 2134' cemented with 200sxs-sr	nd-1/4# flo	seal-2%cc	-20sxs wer		RECEIVED SAS CORPORATION COMMISSION
			·		JUL 2 1 2008
					CONSERVATION DIVISION WICHITA, KS
Action/Recommendations: Follow	Up Required	Yes N	lo [0]	Date:	
Alt.II requirements have been met			<u></u>		
JUL 1 7 2008 Ω					
W -					
Verification Sources Dodge City					Photos Taken:
RBDMS KGS T	A Program	Day. Mia	haal Maiar		
	Courthouse	By: <u>IVIIC</u>	hael Maier		
Other:					

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/28/2008</u>

Date: <u>07/10/08</u>		<u>.</u> .	District:	01	_	License #: 3842		
Op Name: <u>3842</u>			Spot: <u>N</u> E	-SW-SV	V-SE	Sec <u>20 </u>		
County: Lane	ity: Lane Lease			Name: Penka Well #: 1-20				
I.D. Sign Yes	No		n	Gas Ver	nting	Yes No		
Tank Battery Cond		le Overflow	ring s	Pits Fluid D		ft; Approx. Size:ft. xft.		
Pits, Injection Site Fluid Depth:	_ft; Approx. S	ize:ft	. xft.	├ ──`	water Pi s Visible	pelines Tested for Leaks: Y N		
Oil Spill Evidence				Flov	wing Hol	les		
Abandoned Well	Potential Pollu	ntion Problem	Yes No	ТА	Wells			
Lease Cleanliness Very Good S	atisfactory	Poor Very	y Bad	Moi	nitoring l	Records		
SWD/ER Injection Well Permit #: Pr Permit #: Pr Permit #: Pr	ressure – Actua ressure – Actua ressure – Actua	al: psi; Aut al: psi; Aut al: psi; Aut	thorized: psi	Tubing Tubing Tubing	: :	ions		
· API Number	Footages	Spot Location	GPS		Well #	Well Status		
15-101-22,109-0000	340FSL 2250FEL	NE-SW-SW-SE	38.43667-100.5	2448 1	-20	New well, Alt.II completed		

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>