## KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/02/08</u>	District: 01	<u>,                                     </u>	Case #:					
	New Situation	on [	Lease Inspection					
	Response to	Request	Complaint					
	Follow-Up		Field Report					
Onesestan License Nov. 2042	ADI Wali Number	. 15 101 22 112 (	00.00					
Operator License No: <u>3842</u> Op Name: Larson Engineering, Inc. dba Larson Operating Company		: <u>15-101-22,112-(</u> F-SW Sec 16	_Twp_ <u>17_</u> S_Rng_ <u>28</u> E / <b>√\</b>					
Address 1: 562 W State Rd. 4		3cc 10	Feet from N/ S Line of Section					
Address 2:			Feet from E/W Line of Section					
City: Olmitz		054 Long: 100	لنا ليا					
State: Kansas Zip Code: 67564 -8561			Well #: <u>1-16</u>					
Operator Phone #: (620) 653-7368	County: Lane							
Reason for Investigation:								
Witness Alt.II			,					
Problem:								
None cement circulated to surface								
Thome dement circulated to duridee								
Persons Contacted:								
Findings:								
8-5/8" @ 247'W/175sxs cement TD @ 4652'								
5-1/2" @ 4651'W/215sxs cement								
Port Collar @ 2145' cemented with 225sxs-smd-1/4# flo seal-2%cc-15sxs went to pit								
			KANSAS CORPORATION COMMISSIO					
			SEP 1 2 2008					
			CONSERVATION DIVISION WICHITA, KS					
			D.					
	Up Required Y	es No 🔊	Date:					
Alt.II requirements have been met			•					
DECEIVED								
		•						
The same of the sa		· · · · · · · · · · · · · · · · · · ·						
Verification Sources:			Photos Taken:					
	A Program	D Michael Mair						
	ourthouse	By: <u>Michael Maier</u>						
Other:			do					

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>09/02/08</u>		District:	01		License #: 3842		
Op Name: 3842	•	Spot: <u>S/2</u>	Spot: <u>S/2-NE-SE-SW</u> Sec <u>16</u> Twp <u>17</u> S Rng <u>28</u> E  W				
County: Lane		Lease Nai	me: <u>Doris</u>	:: <u>Doris</u> Well #: <u>1-16</u>			
I.D. Sign Yes No		' গ্ৰ	Gas Ventin	g Yes No		নি	
Tank Battery Condition  Condition: Good Question	able Overflow	ring	Pits Fluid Depth	ı:ft; Appr	ox. Size:ft. x	ft.	
Pits, Injection Site			Saltwate	er Pipelines	-	€ E	
Fluid Depth:ft; Approx	x. Size:ft	. xft.	<b>—</b>	sible: Y N	Tested for Leaks:	YN	
Oil Spill Evidence			Flowing	Holes			
Abandoned Well Potential Potential Potential	ollution Problem	Yes No S	TA We				
Lease Cleanliness Very Good Satisfactory	Poor Ver	y Bad	Monitor	ing Records			
SWD/ER Injection Well Yes [	No	Lane 🔄	Gauge Con	nections Yes	No	10	
Permit #: Pressure – Ac	ctual:psi; Au	thorized: psi	Tubing:	; T/C Annul	us:; C/SP Annul	us:	
Permit #: Pressure – Ac					us:; C/SP Annul		
Permit #: Pressure – Ac					us:; C/SP Annul		
	ctual:psi; Au	thorized: psi	Tubing:	; T/C Annul	us:; C/SP Annul	us:	
API Footage	Spot Location	GPS	We	11#	Well Status		
737FSL 15-135-22,112-00-00 2310-FW	/L S/2-NE-SE-SW	38.57054-100.4	2397 1-16	New well, Alt	New well, Alt.II completed		