KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/24/08</u>	District: <u>0</u>	1		Case #	:
	New S	ituation		Lease Insp	ection
	Respo	nse to Request	—	Complaint	
	Follow	v-Up		Field Repo	ort
Operator License No: 4058	API Well N	umber: <u>15-13</u>	5-24 834-0	0-00	
Op Name: American Warrior			•		S Rng 22 E / W
Address 1: P.O. Box 399	_				N/ S Line of Section
Address 2:					E / W Line of Section
City: Garden City		38.42091			
State: Kansas Zip Code: 67846 -0399					Well #: 1-12
Operator Phone #:		less			
Reason for Investigation:	*.* ***				
Witness Alt.II					
Problem:					
None, cement circulated to surface					
Persons Contacted:					CEIVED ORATION COMMISSION
rersons Contacted:			•		
				OCT	0 9 2008
Findings:				CONSER	VATION DIVISION CHITA, KS
8-5/8" @ 227W/160sxs cement					
TD @ 4319'					
5-1/2" @ 4318'W/150sxs cement					
Port Collar @ 1406' cemented with 130sxs-si	md-1/4# flo	seal-2%cc-	10sxs wei	nt to pit	1
Action/Recommendations: Follow	v Up Required	Yes No	×2	Date:	
Alt.II requirements have been met					
MECEIVEN					
OCT - 6 2008					
VI					
Verification Sources: DOCOO City					Di de Trei e e
		1			Photos Taken:
RBDMS KGS	ΓA Program	Rv. Mich	nael Maier		Photos Taken:
RBDMS KGS	ΓA Program Courthouse	By: <u>Mic</u> t	nael Maier		Photos Taken:

Retain I Copy District Office Send I Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>09/24/08</u>			Distric	et: <u>()1</u>		Lice	nse #: <u>4058</u>		
Op Name: 4058			Spot: [Spot: NW-SE-NE-SE Sec 12		Sec <u>12</u> Twp <u>19</u>	Twp 19 S Rng 22 E W		
County: Ness Lease				Name: <u>V Rein</u> Well #: <u>1-12</u>					
I.D. Sign Yes No			<u></u>	Gas	enting	Yes No		Ð	
Tank Battery Condition Condition: Good Questionable Overflowing					its Depth:	ft; Approx. Size	::ft. x	ft.	
Dita Injection Site					altwater Pi	inalinas			
Pits, Injection Site Fluid Depth:ft; /	Approx. Siz	ee:ft	. xft.			·	ested for Leaks:	Y N	
Oil Spill Evidence				F	lowing Hol	les			
Abandoned Well Poter	ntial Pollut	ion Problem	Yes No 🗠]	`A Wells				
] \square M	lonitoring	Records			
Lease Cleanliness Very Good Satisfa	actory	Poor Very	Bad						
SWD/ER Injection Well	Yes N	No	Ness 🖸	Gaug	e Connect	ions Yes No		•7	
Permit #: Pressu	re – Actual	: psi; Aut	horized: ps			; T/C Annulus:			
Permit #: Pressu						; T/C Annulus:			
Permit #: Pressu						; T/C Annulus:			
Permit #: Pressu	re – Actual	: psi; Aut	horized: ps	i Tubi	ng:	; T/C Annulus:	; C/SP Annul	us:	
API Number	ootages	Spot Location	GPS		Well #		Well Status		
335FNL 15-135-24,834-00-00 2291FWL SW-NE-NE-NW 38,42		38.42091-99.7	70643	1-12	New well, Alt.II con	npleted			