

# KCC OIL/GAS REGULATORY OFFICES

Date: 10/17/08

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5086

API Well Number: 15-101-22,115-00-00

Op Name: Pintail Petroleum, Ltd.

Spot: SW-SE-NW-NW Sec 2 Twp 18 S Rng 27  E /  W

Address 1: 225 N Market Ste. 300

1020 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

850 Feet from  E /  W Line of Section

City: Wichita

GPS: Lat: 38.52085 Long: 100.28111 Date: 10/17/08

State: Kansas Zip Code: 67202 -2024

Lease Name: Mauch "JL" Well #: 1-2

Operator Phone #: (316) 263-2243

County: Lane

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None cement circulated to surface

**Persons Contacted:**

**Findings:**

8-5/8" @ 218' W/170sxs  
TD @ 4550'  
4-1/2" @ 4547'W/ 175sxs cement  
Port Collar @ 1997'-cemented with 175sxs-smd-1/4# flo seal-2%cc--20sxs went to pit


RECEIVED  
KANSAS CORPORATION COMMISS  
**OCT 29 2008**  
CONSERVATION DIVISION  
WICHITA, KS

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met.



Verification Sources: \_\_\_\_\_

Photos Taken: \_\_\_\_\_

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 10/17/08

District: 01

License #: 5086

Op Name: 5086

Spot: SW-SE-NW-NW Sec 2 Twp 18 S Rng 27  E  W

County: Lane

Lease Name: Mauch "JL" Well #: 1-2

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness

Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Lane

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-101-22,115-00-00	1020FNL 850FWL	SW-SE-NW-NW	38.52085-100.28111	1-2	New well, Alt. II completed