## KCC OIL/GAS REGULATORY OFFICE

Date 11-5-08	( ) New Situation
Operator license # 31930	( ) Response to Request ( ) Follow-up
Operator Blue RIDGE PETROLEUM	ORP. 15-135-24838-0000
	Location SWSWNWW.Sec 2,T19S,R26W
ENID, OX 73702	Lease ALYSHEBA Well # 6-2
Operator phone number <u>580-242-3732</u>	County <u>NESS</u>
Reason for Investigation: TOP STAGE C	PEMENTING REQUIREMENT
OF AN ALTERNATE II WEL	L COMPLETION.
Problem:	
Person(s) Contacted:	
Findings: 85/8 @ 22/	w/ 165 SX CMT
51/2" @ 4462	w/ 175 SX CMT
	FOUND AT 1853'
SWIFT SER	VICES PUMPED 180 TOTAL SX,
w/ 20 SX	CIRCULATING TO THE PIT
38.43279°N 100.17170°W	photos taken:
Action/Recommendations: ALTERNATE.	II TOP STAGE CEMENTING
REQUIREMENT WAS SATIS.	FACTORILY RECEIVED
MEGELVEN	NOV 1 2 2008
Nov - 6 2008	CONSERVATION DIVISION WICHITA, KS
)Lease Inspection	By Elmei
) Field Report KCC Douge City	ENVIRON. SCIENTIST II
etain 1 copy Joint District Office end one copy Conservation Division	() RBDMS () TA program () KGS () T-1 database
and the state of	

## LEASE INSPECTION

YES [ ] I.D. Sign	NONE COMMENTS
·[ ] Tank Battery	[ ]; Condition: good [ ] questionable [ ] overflowing [ ]
[ ] Pits, tank battery	[ ]; Fluid depth ft.; approx. size ft x ft
[ ] Pit, injection site	[ ]; Fluid depth ft.; approx. size ft x ft
[ ] Gas venting	
[ ] Oil spill evidence	
[ ] Saltwater evidence	[ ]; Surface flow; seepage
[ ] Saltwater pipelines	[ ]; Seepage visible Yes/No; tested for leaks Yes/No
[ ] Flowing holes	[]
[ ] Abandoned wells	[]
[ ] TA wells	[ ]; Potential poll. Prob; currently producing
SWD/ER Injection well SWD/ER Injection well SWD/ER Injection well SWD/ER Injection well	[ ]; Permit #Pressure-actualpsi, Authorizedpsi[ ]; Permit #Pressure-actualpsi, Authorizedpsi[ ]; Permit #Pressure-actualpsi, Authorizedpsi[ ]; Permit #Pressure-actualpsi, Authorizedpsi
[ ] Monitoring records	[ ]
Gauge connections Gauge connections Gauge connections Gauge connections	[ ]: tubing ; T/C annulus ; C/SP annulus [ ]: tubing ; T/C annulus ; C/SP annulus [ ]: tubing ; T/C annulus ; C/SP annulus [ ]: tubing ; T/C annulus ; C/SP annulus ]
Lease cleanliness: Very good	satisfactory poor very bad
WelI number & GPS coordinates:	