KCC OI	L/GAS REGUL	ATORY OF	FICES			
Date: <u>12/17/08</u>	Respon	tuation nse to Request -Up	Lease Ins Complain Field Rep	ort		
Operator License No: 4058  Op Name: American Warrior  Address 1: P.O. Box 399  Address 2:	Spot: <u>NW-</u> 2100 950 GPS: Lat: 3	API Well Number:       15-135-24,856-00-00         Spot:       NW-SE-SW-NW       Sec 18 Twp 19 S Rng 21 [         2100       Feet from ✓ N / S Ling         950       Feet from E / ✓ W L         GPS:       Lat:       38.40161 Long:       99.69244 Date:       12/         Lease Name:       DeWald Well #:       1-18         County:       Ness				
Reason for Investigation: Witness Alt.II			<u> </u>	·		
None, cement circulated to surface						
Persons Contacted:						
Findings:  8-5/8" @ 228W/160sxs cement TD @ 4322' 5-1/2" @ 4321'W/165sxs cement Port Collar @ 1400' cemented with 11	5sxs-smd-1/4# flo	seal-2%cc-10	sxs went to pit			
Action/Recommendations:	Follow Up Required	Yes No	Date: _			
Alt.II requirements have been met  DEC 2 2 2008		•		RECEIVED KANSAS CORPORATION COMMISSION DEC 2 4 2008  CONSERVATION DIVISION WICHITA, KS		
Verification Sources:  RBDMS T-I Database  Other:	TA Program Courthouse	By: <u>Michae</u>	el Maier	Photos Taken:		
				-		

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>12/17/08</u>		<del>_</del>	Distric	t: <u>01</u>		Li	cense #: <u>4058</u>			
Op Name: 4058  County: Ness			Spot: <u>N</u>	W-SE-	SW-NW	Sec <u>18</u> Twp <u>1</u>	p <u>19</u> S Rng <u>21</u> E 🕢 W			
			Lease N	Lease Name: <u>DeWald</u>			Well #: <u>1-18</u>	18		
I.D. Sign Yes	No		87	Gas	Venting [	Yes No		٤٦		
Tank Battery Cond Condition: Good		ble Overflov	ving 🔊		its   Depth: _	ft; Approx. S	ize:ft. x	ft.		
Pits, Injection Site		· · · · · · · · · · · · · · · · · · ·			altwater P	ripelines		87 k7		
Fluid Depth:	_ft; Approx. S	Size:fi	t. xft.	Le	aks Visible	e: Y N	Tested for Leaks:	Y N		
Oil Spill Evidence				F	lowing Ho	les				
Abandoned Well	Potential Poll	ution Problem [	Yes No 🔊	7	A Wells					
					Monitoring Records					
Lease Cleanliness Very Good Sa	atisfactory	Poor Ver	ு y Bad	<u> </u>	3					
SWD/ER Injection Well Permit #: Pr		•	Ness 🔄	_		tions Yes No	; C/SP Annulus	· ·		
Permit #: Pr							; C/SP Annulus			
Permit #: Pr	essure – Actu	al: psi; Au	thorized: psi	Tubi	ng:	; T/C Annulus:	; C/SP Annulus	:		
Permit #: Pr	essure – Actu	al: psi; Au	thorized: psi	Tubi	ng:	; T/C Annulus:	; C/SP Annulus	:		
API Number	Footages	Spot Location	GPS		Well #		Well Status			
15-135-24,856-00-00	2100FNL 950FWL	NW-SE-SW-NW	38.40161-99.6 <sup>9</sup>	9244	1-18	New well, Alt.II co	mpleted			
							<u>,,,,</u>			
1										
				<u> </u>				•		