| KCC OIL/GAS REGULATORY OFFICES | | | | | | | | | | |
|---|---|--------------------|----------------|--|--|--|--|--|--|--|
| Date: 12/16/08 | Follow-U | e to Request Jp | Leas Com Field | Case #:e Inspection plaint I Report | | | | | | |
| Operator License No: 30742 Op Name: Palomino Petroleum, Inc. Address 1: 4924 SE 84th St. Address 2: City: Newton State: Kansas Zip Code: 67114 _8827 Operator Phone #: (316) 799-1000 | Spot: <u>NW-N</u> 1170 2080 GPS: Lat: <u>38</u> | .58420Lo | Feet 100.114 | | | | | | | |
| Reason for Investigation: Witness Alt.II | | | | | | | | | | |
| Persons Contacted: Findings: 8-5/8" @ 214'W/165sxs cement TD @ 4570' 5-1/2" @ 4568'-cemented with 160sxs cem Port Collar @ 1851' cemented with 180sxs | ent -smd-1/4# flo s | eal-2%cc-15 | sxs went to | pit | | | | | | |
| Action/Recommendations: Fol | llow Up Required | Yes No |) Da | te: | | | | | | |
| None Alt.II requirements have been met. DEC 2 2 20080 | - | | | RECEIVEL KANSAS CORPORATION COMMISSION DEC 2 4 2008 CONSERVATION DIVISION WICHITA, KS | | | | | | |
| Verification Sources: RBDMS KGS T-I Database District Files Other: Retain 1 Copy District Office Send 1 Copy to Conservation Division | TA Program Courthouse | By: Michae | el Maier | Photos Taken: | | | | | | |

Form: _

| Date: <u>12/16/08</u> | | _ | Distric | et: 01 | | Lic | ense #: <u>30742</u> | | | | |
|--|-----------------|------------------|----------------|---------------|---|---------------------------|----------------------|--------|--|--|--|
| Op Name: 30742 | | | Spot: <u>1</u> | NW-NE- | SE-SW_ | Sec <u>8</u> Twp <u>1</u> | 7 S Rng 25 | E | | | |
| County: Ness | | Lease N | Name: Stu | ıtz "H" | | Well #: <u>4</u> | | | | | |
| I.D. Sign Yes | No | | (c) | Gas V | enting Y | es No | | ۲C) | | | |
| Tank Battery Condition Condition: Good Questionable Overflowing Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. x | | | | | Pits Fluid Depth:ft; Approx. Size:ft. xft. | | | | | | |
| | | | | | Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N | | | | | | |
| Oil Spill Evidence | | | | Flowing Holes | | | | | | | |
| Abandoned Well | Potential Pollu | ition Problem | Yes No S | Т | A Wells | | | | | | |
| Lease Cleanliness Very Good Satisfactory Poor Very Bad | | | | М | Monitoring Records | | | | | | |
| SWD/ER Injection Well | Yes | No . | « C | Gauge | e Connections | Yes No | | k7) | | | |
| Permit #: Pr | essure – Actua | ıl: psi; A | uthorized: ps | i Tubin | ıg: | ; T/C Annulus: | ; C/SP An | nulus: | | | |
| Permit #: Pr | | | | | | ; T/C Annulus: | | | | | |
| Permit #: Pr | | | | | | ; T/C Annulus: | | | | | |
| Permit #: Pr | essure – Actua | ıl: psi; A | uthorized: ps | i Tubin | ıg: | ; T/C Annulus: | ; C/SP An | nulus: | | | |
| API Number | Footages | Spot Location | GPS | | Well Number | | Well Status | | | | |
| 15-135-24,867-0000 1170FSL-2080FWL NW-NE-SE-SW 38.5842 | | 38.58420-100.1 | 1410 | 4 | New well, Alt,I | I completed | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | <u> </u> | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: _____