

KCC OIL/GAS REGULATORY OFFICE

Date 1/2/09

- New Situation
- Response to Request
- Follow-up

Operator license # 9067

Operator Damar Resources, Inc.

234 W. 11th, Ste. A

Address P.O. Box 70

Location NE-SE-NW-SE, Sec 11, T 21 S, R 24 W

Hays, KS 67601-3805

Lease Hollenbeck "A" Well # 1

County Hodge man

Operator phone number 785-625-0020

15-083-21575-0000

Reason for Investigation: Company requested a witness to the Alternate II cementing job.

Problem: Alternate II cementing requirements have not been met.

Person(s) Contacted: _____

Findings: 8 7/8" set @ 303' @ 190 sx cont. 5 1/2" set @ 4512' @ 150 sx on primary cementing job. Company opened part collar @ 1545'. Swift Services, Inc. pumped 125 sx SMP. Circulated 15 sx to pit. Closed part collar.

RECEIVED
KANSAS CORPORATION COMMISSION


JAN 09 2009

CONSERVATION DIVISION
WICHITA, KS

GPS-38.23831°N, 99.92294°W photos taken: _____

Action/Recommendations: None. Alternate II cementing requirements have been met.

- Lease Inspection
- Complaint
- Field Report



By Eui Matheson

Retain 1 copy Joint District Office
Send one copy Conservation Division

- RBDMS
- TA program
- KGS
- T-1 database
- District files
- Courthouse

LEASE INSPECTION

YES

NONE COMMENTS

- [] I.D. Sign []
- [] Tank Battery []; Condition: good [] questionable [] overflowing []
- [] Pits, tank battery []; Fluid depth ____ ft.; approx. size ____ ft x ____ ft
- [] Pit, injection site []; Fluid depth ____ ft.; approx. size ____ ft x ____ ft
- [] Gas venting []
- [] Oil spill evidence []
- [] Saltwater evidence []; Surface flow _____; seepage _____
- [] Saltwater pipelines []; Seepage visible Yes/No; tested for leaks Yes/No
- [] Flowing holes []
- [] Abandoned wells []
- [] TA wells []; Potential poll. Prob. _____; currently producing _____
- [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- [] SWD/ER Injection well []; Permit # _____ Pressure-actual _____ psi, Authorized _____ psi
- [] Monitoring records []
- [] Gauge connections []; tubing _____; T/C annulus _____; C/SP annulus _____
- [] Gauge connections []; tubing _____; T/C annulus _____; C/SP annulus _____
- [] Gauge connections []; tubing _____; T/C annulus _____; C/SP annulus _____
- [] Gauge connections []; tubing _____; T/C annulus _____; C/SP annulus _____

Lease cleanliness: Very good _____ satisfactory _____ poor _____ very bad _____

Well number & GPS coordinates:
