

15-051-01257-00-00  
DISTRICT CONSERVATION AGENT'S REPORT

*R*

TO:

State Corporation Commission  
Conservation Division  
211 North Broadway  
Wichita, Kansas

FILE NO. 146-3  
LOCATION CN 1/2 NW NW  
SEC. 17 TWP. 11 RGE. 20W

Dry Hole  Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have this date completed supervision of plugging of:

Well No. 1 Lease Thayer

Operator Coppinger Drg Co Address 507 517 Union Natl Bldg Wichita,

Field \_\_\_\_\_ County Ellis

Total Depth 3650 Feet.

Plugging Contractor same

Plugging Contractor's License No. \_\_\_\_\_

Address \_\_\_\_\_  
(Describe briefly the manner in which the well was plugged)

8 5/8" at 330' circulated with cement.

Gunned pits, filled hole with heavy mud, pumped cementing plug to 320', followed by 100 sax cement - cement 320' to 0'.

Cementing by Halliburton Cementing Co.

*Edward Petty*  
District Conservation Agent  
STATE CORPORATION COMMISSION  
Date 3-8-57

MAR 12 1957  
3-12-1957  
CONSERVATION DIVISION  
WICHITA, KANSAS

PLUGGING  
FILE SEC 17 T. 11 R. 20W  
BOOK PAGE 146 LINE 3