DISTRICT CONSERVATION AGENT'S REPORT



TO:

15-065-00953-00-00

State Corporation Commission Conservation Division 211 North Broadway Wichita, Kansas

211 North Broadway			FILE NO.			
Vichita, Kansas			LOCATION	SE SE	NE	
			SEC. 10	TWP.10	_RGE	23
Ory Hole X Abandoned Oil We	11		Abandoned	Cas Well		
I have this date completed supervision of	plugging	of:	4			
Vell No. lease L	aw					
perator Burch Drg Co Inc.	_Address	1011	Union Ce	n Bldg	Wichi	ta,
Field	County_	Graha	m			
1165	Feet.					
Plugging Contractor same						
Plugging Contractor's License No.						
address						
(Describe Briefly the manner 8 5/8" at 210' circulated with a		ch the	well was p	lugged)		
Gunned pkts, circulated hole wi	th heavy	mud,	set ceme	enting	nlug a	t
600', displaced 20 sax cement the	nrough d	lrill	pipe, hea	a v y mud	to	
200', set cementing plug and 20	sax cen	ent d	isplaced	throug	h dril	1
pipe, heavy mud to 40', set ceme	enting p	olug,	1/2 sack	hulls	and 10	D
sax cement to bottom cellar.						
						
		Lean	1 /200	ucu · ·		
· · · · · · · · · · · · · · · · · · ·		Distri		ation Ag	ent	
	Date	8-	30-57			

PLUGGING

FILE SEC 10 T to R 23W

BOOK PAGE 41 LINE 40