DISTRICT CONSERVATION AGENT'S REPORT	A. C.
TO:	
State Corporation Commission Conservation Division	
211 North Broadway FILE NO	
LOCATION_SW	SW NW
SEC. 13 TWP.	9 RGE. 24
Dry Hole X Abandoned Oil Well Abandoned Gas Well	
I have this date completed supervision of plugging of:	
Well No. 1 Lease Hildebrand 1006 Central	Bldg.
Well No. 1 Lease Hildebrand 1006 Central Operator K & E Drg, # One, Address Wichita, ans	<i>-</i>
FieldCountyGraham	
Total Depth 4030 Feet.	
Plugging Contractorsame	
Plugging Contractor's License No	
(Describe briefly the manner in which the well was plug	ged)
8 5/8" at 228! circulated with cement.	
Circulated hole with heavy mud, set cementing plug at 210	, 1/2
sack hulls and 15 sax cement, mud to 40', set cementing pl	ug, 1/2
sack hulls and 10 sax cement to bottom cellar.	
	$\overline{}$
JAN 1 806 Date 1-8-56	on Agent
Date	

DOOK PAGE 30 LINE 39

agnoen varion division Wichita, Kansas