

CLOSURE OF SURFACE PIT

Operator Name: Noble Energy, Inc.	License Number: 33190
Operator Address: 100 GLENBOROUGH DR STE 100 HOUSTON TX 77067 3618	
Contact Person: Jennifer Barnett	Phone Number: (303) 228 - 4235
Permit Number (API No. if applicable): 15-023-21100-00-00	Lease Name & Well No.: Bursch 22-27
Type of Pit: <input type="checkbox"/> Emergency Pit <input type="checkbox"/> Burn Pit <input type="checkbox"/> Settling Pit <input checked="" type="checkbox"/> Drilling Pit <input type="checkbox"/> Workover Pit <input type="checkbox"/> Haul-Off Pit	Pit Location (QQQQ): NW SW SE NW Sec. <u>27</u> Twp. <u>5</u> R. <u>38</u> <input type="checkbox"/> East <input checked="" type="checkbox"/> West <u>2214</u> Feet from <input checked="" type="checkbox"/> North / <input type="checkbox"/> South Line of Section <u>1570</u> Feet from <input type="checkbox"/> East / <input checked="" type="checkbox"/> West Line of Section <u>Cheyenne</u> County
Date of closure: <u>1/22/2009</u>	
Was an artificial liner used? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Sealed with clay soil, native and fresh mud.	
Abandonment procedure of pit: Drill cuttings are stirred with a trac-hoe, allow liquids to evaporate, let cuttings dry and backfill.	

Submitted Electronically