RECEIVED
STATE CORPORATION COMMISSION

state corporation commission

Conservation division agent's report Conservation division Wichita, Kansas

Jewel M. Ogden, Director 500 Insurance Building 212 North Market

Location: NW SE SW Name of Field: I have this date completed supervision of Bowlby Lease Name: Operator's Full Name: Complete Address: Plugging Contractor: Leben Drg Co	Sec. 14	Twp. 11 r	3430	nnessaniet meet van die sied die State deutsplaas opweld de samme
Name of Field: I have this date completed supervision of Bowlby Lease Name: Operator's Full Name: Okmar Oil Co Complete Address: 820 Union Nat	plugging of	Total Depth:	3430	nnessaniet meet van die sied die State deutsplaas opweld de samme
Name of Field: I have this date completed supervision of Bowlby Lease Name: Operator's Full Name: Okmar Oil Co Complete Address: 820 Union Nat	plugging of	Total Depth:	3430	nnessaniet meet van die sied die State deutsplaas opweld de samme
Lease Name: Bowlby Operator's Full Name: Okmar Oil Co Complete Address: 820 Union Nat	Coloratoric suspension of Management State (Coloratoric State (Colorat	•	We 7	
Operator's Full Name: Okmar Oil Co Complete Address: 820 Union Nat			MO 0	
Complete Address: 820 Union Nat				
Plugging Contractor: Leben Drg Co	tl Wichi	ta, Kans		
Address: Wichita, Kans	S.	Licen	lee No	
Oll Well Gas Well Input of Other well as hereafter indicated:	Well_	SWD Well	D & 1	A x
Was any delay in plugging operations cause	d by Conserv	vetion Divisio	on Agent? Yo	esNo
	·	,		
Operation Completed: Hour 9AM Day The above well was plugged as follows:	y 9 '	Month	LO .:	Year_5
8 5/8" 163; circulated with cement.		·	·	
Circulated hole with heavy mud, setcem	nenting pla	ug at 600'.	displaced	20 sax
cement through drill pipe, heavy mud t				
displaced 20 sax cement through drillp	•		: 1	
plug, 1/2 sack hulls and 10 sax cement				
Cementing by Sun Cementing Co.	٠			
				,
	 			
	9.0	2		
	Signed:	Conservati	- ILLE	