

KANSAS  
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

5-3-1961

TO:  
Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: Ellis  
Location: SW SW SE Sec. 29 Twp. 11 Rge. 19 (E) (W) \_\_\_\_\_  
Name of Field: \_\_\_\_\_ Total Depth: 3761

I have this date completed supervision of plugging of:

Lease Name: Solomon Well No. 1  
Operator's Full Name: Woodman & Iannitti  
Complete Address: 714 Union Natl Bk Bldg Wichita, Kansas  
Plugging Contractor: same  
Address: \_\_\_\_\_ License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A

Other well as hereafter indicated: \_\_\_\_\_

Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 12 Noon Day 28 Month 4 Year 61

The above well was plugged as follows:

8 5/8" 184' circulated with cement.  
circulated hole with heavy mud, set cementing plug at 600', displaced 20  
sax cement through drill pipe, heavy mud to 180', displaced 20 sax cement  
through drill pipe at 180', heavy mud to 40', set plug, 1/2 sack hulls and 10  
sax cement to bottom cellar.

Signed: [Signature]  
Conservation Division Agent

Reviewed: [Signature]  
Field Supervisor

Remarks:

INVOICED  
DATE 5/11/61  
INV. NO. 5063-W