

15-051-00814-00-00

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NW NW SW

SEC. 24 TWP. 11 RGE. 20

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. C-1 Lease Davis

Operator Herndon Drg Co Address 423 Mayo Bldg Tulsa, Okla

Field _____ County Ellis

Total Depth 3675 Feet.

Plugging Contractor Same & Sun Cementing Co

Plugging Contractor's License No. _____

Address _____

(Describe briefly the manner in which the well was plugged)

8 5/8" at 190' circulated with cement.

Filled hole with heavy mud, pumped cementing plug to 190',

followed by 60 sax cement - cement 190' to bottom cellar.

Cementing by Sun Cementing Co.

Edson P. Kelly
District Conservation Agent

Date 2-8-56

RECEIVED
COMMISSION

2-14-1956

CONSERVATION DIVISION
Wichita, Kansas

PLUGGING
FILE SEC 24 T 11 R 20 W
BOOK PAGE 38 LINE 27