

15-051-00668-00-00

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION SW SW SW

SEC. 24 TWP. 11 RGE. 20 W

Dry Hole x Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1 Lease Davis *524 Mayo Bldg*

Operator Herndon Drg Co Address Lyons, Kans

Field _____ County Ellis

Total Depth 3775 Feet.

(Describe briefly the manner in which the well was plugged)

8 5/8" at 270' circulated with cement.

Circulated hole with heavy rotary mud, pushed Halliburton plug to 240', displaced 15 sax cement, pumped through drill pipe, rotary mud to 35', set Halliburton plug and 10 sax cement to bottom cellar.

Cementing by Halliburton Co.

PLUGGING
FILE SEC 24 T 11 R 20 W
BOOK PAGE 68 LINE 41

RECEIVED
STATE CORPORATION COMMISSION
3-23-1951
MAR 23 1951

[Signature]
District Conservation Agent

Date 3-22-51