

KCC OIL/GAS REGULATORY OFFICES

Date: 03/18/09

District: 01

Case #: _____

- New Situation
 Response to Request
 Follow-Up

- Lease Inspection
 Complaint
 Field Report

Operator License No: 4058

API Well Number: 15-135-24,879-00-00

Op Name: American Warrior

Spot: NW-SW-SE-SW Sec 12 Twp 19 S Rng 22 E / W

Address 1: P.O. Box 399

365 Feet from N / S Line of Section

Address 2: _____

1360 Feet from E / W Line of Section

City: Garden City

GPS: Lat: 38.40827 Long: 99.70949 Date: 3/18/09

State: Kansas Zip Code: 67846 -0399

Lease Name: Dauber Well #: 1-12

Operator Phone #: _____

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @ 225W/165sxs cement
TD @ 4355'
5-1/2" @ 4353'W/145sxs cement
Port Collar @ 1441' cemented with 120sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

RECEIVED
KANSAS CORPORATION COMMISSION
APR 02 2009
CONSERVATION DIVISION
WICHITA, KS

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alt.II requirements have been met

RECEIVED

MAR 25 2009

KCC DODGE CITY

Verification Sources:

- RBDMS KGS TA Program
 T-I Database District Files Courthouse
 Other: _____

Photos Taken: _____

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 03/18/09

District: 01

License #: 4058

Op Name: 4058

Spot: NW-SW-SE-SW Sec 12 Twp 19 S Rng 22 E W

County: Ness

Lease Name: Dauber Well #: 1-12

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.879-00-00	365FSL 1360FWL	NW-SW-SE-SW	38.40827-99.70949	1-12	New well. Alt. II completed