

Date 3/17/2009

- New Situation
- Response to Request
- Follow-up

Operator license # 4058

Operator American Warrior, Inc.

Address 3118 Cummings Rd.  
Garden City, KS 67846

Location NWNESENE, Sec 24, T 22 S, R 24 W

Lease W. Bradshaw Well # 1-24

County Hodgeman  
API # 15-083-21593-00-00

Operator phone number 620-275-7461

Reason for Investigation: Witness Alternate II completion

Problem: None: Cement circulated to surface and stayed

Person(s) Contacted: \_\_\_\_\_

Findings: 8 5/8" @ 221'  
5 1/2" @ 4697'  
T.D. @ 4698

RECEIVED  
KANSAS CORPORATION COMMISSION  
MAR 23 2009  
CONSERVATION DIVISION  
WICHITA, KS

Port Collar @ 1,649' cemented with 150 sks.  
of SMD with 1/4" Flo-seal with 20 sks. to pit. Swift Services  
Southwest well service over the hole.

photos taken: \_\_\_\_\_

Action/Recommendations: None: Alternate II requirements have been met

cement to surface and stayed  
well @ { 38.12744 °N  
-99.90062 °W

- Lease Inspection
- Complaint
- Field Report

RECEIVED  
MAR 18 2009

By Jerry W. Stjepic  
PART II

KCC DODGE CITY

Retain 1 copy Joint District Office  
Send one copy Conservation Division

- RBDMS
- KGS
- District files
- TA program
- T-1 database
- Courthouse

LEASE INSPECTION

YES

NONE COMMENTS

- [ ] I.D. Sign [ ]
- [ ] Tank Battery [ ]; Condition: good [ ] questionable [ ] overflowing [ ]
- [ ] Pits, tank battery [ ]; Fluid depth \_\_\_\_ ft.; approx. size \_\_\_\_ ft x \_\_\_\_ ft
- [ ] Pit, injection site [ ]; Fluid depth \_\_\_\_ ft.; approx. size \_\_\_\_ ft x \_\_\_\_ ft
- [ ] Gas venting [ ]
- [ ] Oil spill evidence [ ]
- [ ] Saltwater evidence [ ]; Surface flow \_\_\_\_\_; seepage \_\_\_\_\_
- [ ] Saltwater pipelines [ ]; Seepage visible Yes/No; tested for leaks Yes/No
- [ ] Flowing holes [ ]
- [ ] Abandoned wells [ ]
- [ ] TA wells [ ]; Potential poll. Prob. \_\_\_\_\_; currently producing \_\_\_\_\_
- [ ] SWD/ER Injection well [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
- [ ] SWD/ER Injection well [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
- [ ] SWD/ER Injection well [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
- [ ] SWD/ER Injection well [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
- [ ] Monitoring records [ ]
- [ ] Gauge connections [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
- [ ] Gauge connections [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
- [ ] Gauge connections [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
- [ ] Gauge connections [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_

Lease cleanliness: Very good \_\_\_\_\_ satisfactory \_\_\_\_\_ poor \_\_\_\_\_ very bad \_\_\_\_\_

Well number & GPS coordinates:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_
