

# KCC OIL/GAS REGULATORY OFFICES

Date: 11/17/08

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-24,859-00-00

Op Name: American Warrior

Spot: N/2-N/2-S/2-S/2 Sec 13 Twp 19 S Rng 22  E /  W

Address 1: P.O. Box 399

1200 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

2640 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.39613 Long: 99.70508 Date: 11/17/08

State: Kansas Zip Code: 67846 -0399

Lease Name: Schwien-Moore Well #: 1

Operator Phone #: \_\_\_\_\_

County: Ness

### Reason for Investigation:

Witness Alt.II

### Problem:

None, cement circulated to surface

### Persons Contacted:

\_\_\_\_\_

### Findings:

8-5/8" @ 222W/160sxs cement  
TD @ 4349'  
5-1/2" @ 4348'W/155sxs cement  
Port Collar @ 1434' cemented with 165sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

RECEIVED  
KANSAS CORPORATION COMMISSION  
DEC 01 2008  
CONSERVATION DIVISION  
WICHITA, KS

### Action/Recommendations:

Follow Up Required  Yes  No  \*


Date: \_\_\_\_\_

Alt.II requirements have been met

### Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division



Photos Taken: \_\_\_\_\_

By: Michael Maier

Form: 02/22/2008

Date: 11/17/08

District: 01

License #: 4058

Op Name: 4058

Spot: N/2-N/2-S/2-S/2 Sec 13 Twp 19 S Rng 22  E  W

County: Ness

Lease Name: Schwien-Moore Well #: 1

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.859-00-00	1200FSL 2640FEL	N/2-N/2-S/2-S/2	38.39613-99.70508	1	New well, Alt. II completed