

KCC OIL/GAS REGULATORY OFFICES

Date: 10/31/08

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058  
 Op Name: American Warrior  
 Address 1: P.O. Box 399  
 Address 2:  
 City: Garden City  
 State: Kansas Zip Code: 67846 -0399  
 Operator Phone #: \_\_\_\_\_

API Well Number: 15-135-24,854-00-00  
 Spot: SE-SE-NW-SW Sec 7 Twp 19 S Rng 21  E /  W  
 1380 Feet from  N /  S Line of Section  
 1250 Feet from  E /  W Line of Section  
 GPS: Lat: 38.41122 Long: 99.69160 Date: 10/31/08  
 Lease Name: DeWald Well #: 1-7  
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8" @ 227W/160sxs cement  
 TD @ 4315'  
 5-1/2" @ 4314'W/150sxs cement  
 Port Collar @ 1407' cemented with 130sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

RECEIVED  
 KANSAS CORPORATION COMMISSION  
 NOV 19 2008  
 CONSERVATION DIVISION  
 WICHITA, KS

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

RECEIVED  
 NOV 12 2008

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS District Files
- TA Program Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier

Retain 1 Copy District Office  
 Send 1 Copy to Conservation Division

Date: 10/31/08

District: 01

License #: 4058

Op Name: 4058

Spot: SE-SE-NW-SW Sec 7 Twp 19 S Rng 21  E  W

County: Ness

Lease Name: DeWald Well #: 1-7

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.854-00-00	1380FSL 1250FWL	SE-SE-NW-SW	38.41122-99.69160	1-7	New well, Alt. II completed