Date: <u>04/01/09</u>	District: 01	Case #:				
	New Situation	Lease Inspection				
	Response to Request	Complaint				
	Follow-Up	Field Report				
Operator License No: 4058	API Well Number: <u>15-135-24,886-00-00</u> Spot: <u>70'S of NW-SW-NW</u> Sec <u>23</u> Twp <u>18</u> S Rng <u>26</u> ■ E / ✓					
Op Name: American Warrior						
Address 1: P.O. Box 399		Feet from N/ S Line of Section				
Address 2:	335	Feet from E/W Line of Section				
City: Garden City	GPS: Lat: <u>38.47475</u> Lo	ong: <u>100.17194</u> Date: <u>4/1/09</u>				
State: Kansas Zip Code: 67846 -0399	Lease Name: <u>Keith</u>	Well #: <u>1-23</u>				
Operator Phone #:	County: Ness					
Reason for Investigation:						
Witness Alt.II						
Problem:						
None, cement circulated to surface						
Persons Contacted:		KANSAS (Com Colonia) SSION				
		MANAGEMENT 1 F 2000				
		AND US CASON				
Findings:	4.5	CO Maria in The Control of the Contr				
8-5/8" @ 220 //160sxs cement TD @ 4492' 5-1/2" @ 4486'W/175sxs cement Port Collar @ 1857' cemented with 125sxs-	-smd-1/4# flo seal-2%cc-10s	sxs went to pit				
		z				

Action/Recommendations:	Follow Up Required Yes No	je j	Date:
Alt.II requirements have been met			
RECEIVED APR - 7 2009			
•			

KCC DODGE CITY

Verification Sources:

RBDMS

T-I Database

Other:

| Courthouse | By: Michael Maier | Michael Mai

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>04/01/09</u>		_	Dis	strict: <u>01</u>		Lic	cense #: <u>4058</u>	
Op Name: 4058			Spo	ot: <u>70'S o</u>	<u>f NW-SW-N</u>	<u>W</u> Sec <u>23</u> Twp <u>18</u>	8	. 🕢 w
County: Ness			Lea	ase Name:	Keith		Well #: <u>1-23</u>	
I.D. Sign Yes	No			G	as Venting	Yes No		(x)
Tank Battery Cond		ole Overflow	/ing	ъэ FI	Pits luid Depth:	ft; Approx. Si	ze:ft. x	ft.
Pits, Injection Site				TE	Saltwater P	ipelines	•	ស ស
Fluid Depth:	_ft; Approx. S	Size:f	t. x1	ft.	Leaks Visible	e: Y N	Tested for Leaks: Y	N N
Oil Spill Evidence					Flowing Ho	les		
Abandoned Well	Potential Poll	ution Problem [Yes No		TA Wells		•	
					Monitoring	Records		
Lease Cleanliness Very Good S	atisfactory [Poor Ver	y Bad					
SWD/ER Injection Well	Yes	No	Ness	- G	auge Connect	ions Yes No		[3]
Permit #: P	ressure – Actu	al: psi; Au	thorized:				; C/SP Annulus: _	
Permit #: P							; C/SP Annulus: _	
Permit #: P							; C/SP Annulus: _	
Permit #:P	ressure – Actu	al: psi; Au	thorized:	_ psi Tu	ubing:	; T/C Annulus:	; C/SP Annulus: _	
API Number	Footages	Spot Location	G	PS	Well #		Well Status	
15-135-24,886-00-00	1720FNL 335FWL	70'S-of-NW-SW-NW	38.47475-1	100.1719	1-23	New well, Alt.II co	mpleted	
						18 A . 3		
						1977 He 1 1 2		
100 May 100 Ma								
					<u> </u>			