## KCC OIL/GAS REGULATORY OFFICES

Date: <u>03/31/09</u>	District: 01	_	Case #:			
	New Situation	n 🗆	Lease Inspection	I		
	Response to I	Request	Complaint			
	Follow-Up		Field Report	* # *		
Operator License No: 4058	API Well Number: <u>15-135-24,889-00-00</u>					
Op Name: American Warrior		· ·		ng 21 □E /√W		
Address 1: P.O. Box 399				/ S Line of Section		
Address 2:				/ W Line of Section		
City: Garden City		682 Long: <u>99.</u>		eate: 3/31/09		
State: Kansas Zip Code: 67846 -0399		hel				
Operator Phone #:						
Reason for Investigation:						
Witness Alt.II						
Problem:						
None, cement circulated to surface						
Persons Contacted:	-					
Findings:						
	· · · · · · · · · · · · · · · · · · ·	<del></del>				
8-5/8" @ 225W/165sxs cement TD @ 4365'						
5-1/2" @ 4364'W/175sxs cement	•			New Mess		
Port Collar @ 1423' cemented with 125sxs-sr	md-1/4# flo seal-	2%cc-10sxs we	nt to pit	A Company of the same of the s		
_			KANS	Maria de maria de la maria del maria del maria de la maria della d		
			•	All Will I ell and another		
				SN AS		
				COMPANICHITA, KS		
	Up Required Yes	s No	Date:			
Alt.II requirements have been met						
RECEIVED (						
RECEIVED APR - 7 2009						
KCC DODGE CITY						
Verification Sources:	V-60.		Di -	J		
			Phot	os Taken:		
	A Program Bourthouse	y: <u>Michael Maier</u>				
Other:	Courthouse					
Relain I Conv District Office						

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: 03/31/09		_	District:	01	Lice	nse #: <u>4058</u>		
Op Name: 4058			Spot: <u>SV</u>	V-SE-NE-SW	Sec <u>17</u> Twp <u>19</u>	S Rng <u>21</u> _ E 🕢 W		
County: Ness			Lease Na	ame: Rachel Well #: 1-17				
I.D. Sign Yes	No		ব	Gas Venting	Yes No	5		
Tank Battery Condi		le Overflow	ing so	Pits Fluid Depth:	ft; Approx. Size	::ft. xft.		
Pits, Injection Site Fluid Depth:	ft; Approx. S	iize:ft	. xft.	Saltwater P Leaks Visible	<u> </u>	ested for Leaks: Y N		
Oil Spill Evidence				Flowing Ho	les			
Abandoned Well	Potential Poll	ution Problem	Yes No 🔄	TA Wells				
				Monitoring Records				
Lease Cleanliness Very Good S	atisfactory	Poor Very	y Bad					
SWD/ER Injection Well	Yes	No	Ness 🔊		tions Yes No	ফ		
Permit #: Pr						; C/SP Annulus:		
Permit #:Pi						; C/SP Annulus: ; C/SP Annulus:		
	ressure – Actu ressure – Actu		thorized: psi thorized: psi			; C/SP Annulus:		
Termen.								
API Number	Footages	Spot Location	GPS	Well #		Well Status		
1375FSL 15-135-24,889-00-00 2020FWL SW-SE-NE-SW 38.39		38,39682-99.67	7033 1-17	New well, Alt.II completed				
					A 8 8 8 8			
					. % %			
				And the second second				
	<u></u>		<u> </u>					