

KCC OIL/GAS REGULATORY OFFICES

Date: 04/09/09

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-24,890-00-00

Op Name: American Warrior

Spot: 45°N&130°EofN/2-NW-SW-NW-NE-NW Sec 17 Twp 19 S Rng 21  E /  W

Address 1: P.O. Box 399

615 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

1450 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.40587 Long: 99.67239 Date: 4/9/09

State: Kansas Zip Code: 67846 -0399

Lease Name: Rachel Well #: 2-17

Operator Phone #: \_\_\_\_\_

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @ 220W/175sxs cement  
 TD @ 4326'  
 5-1/2" @ 4325"W/175sxs cement  
 Port Collar @ 1398' cemented with 145sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

RECEIVED  
 APR 22 2009  
 KCC WICHITA

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

RECEIVED

APR 20 2009

KCC DODGE CITY

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 04/09/09

District: 01

License #: 4058

Op Name: 4058

Spot: 45°N&130°EofN2-NW-SW-NW-NE-NW Sec 17 Twp 19 S Rng 21  E  W

County: Ness

Lease Name: Rachel Well #: 2-17

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.886-00-00	1720FNL 335FWL	70'S-of-NW-SW-NW	38.47475-100.17194	1-23	New well, Alt. II completed