OTINGES KERROTET OK A ORRICE Date 4/23/09 () New Situation (Response to Request Operator license # 4058) Follow-up Operator American Warrior, Inc. API#15-135-24893-00-00 Address P.O. Box 399 Location SU-NE-NE-NE, Sec 6, T 19 S, R 21 W Garden City, KS 67846 Lease V. Strecker Well # 3-6 County Ness Operator phone number <u>620 - 275 - 7461</u> Reason for Investigation: Operator requested a witness to the Alternate It comorting job Problem: Alternate # comenting requirements have not been met Person(s) Contacted: Findings: 878" set @ 232' @ 165 sx cont. Company opened port collar @ 1392' Swift Services. Inc. pumped 140 sx SMD cmt, circulating 15 x to pit Closed part collar. KANSAS CORPORATION COMMISSION MAY 0 6 2009 RECEIVED GPS-38,43545°N,99,67924 photos taken: Action/Recommendations: None, Alternate II comenting requirements have been mot. RECEIVED)Lease Inspection By Eni Mufaren MAY - 4 2009)Complaint) Field Report KCC DODGE CITY Retain I copy Joint District Office) RBDMS () TA program S end one copy Conservation Division) KGS) T-1 database) District files) Courthouse

LEASE INSPECTION ...

[] Tank Battery []; Condition: good [] questionable [] overflowing [] [] Pits, tank battery []; Fluid depth _ ft.; approx_size ft x ft [] Pits, imjection site. []; Fluid depth _ ft.; approx_size ft x ft [] Gat venting [] [] Oil spill evidence [] [] Saltwater evidence []; Surface flow; seepage [] Saltwater pipelines []; Seepage visible Yes/No; tested for leaks Yes/No [] Flowing holes [] [] JA wells []; Potential poll: Prob; outrently producing [] SWD/ER Injection well []; Permit # Pressure-actual	YES []I.D. Sign	NONE COMMENTS		
[] Pit, injection site. []; Fluid depthft.; approx. sizeft xft [] Gas venting	·[] Tank Battery	[]; Condition: good []	questionable [] overflowing []	
[] Gas venting	[] Pits, tank battery	[]; Fluid depth ft ; a	pprox. sizeft xft	
[] Oil spill evidence	[] Pit, injection site	[]; Fluid depth ft.; ap	pprox. sizeft xft	
[] Saltwater evidence	[] Gas venting			
[] Saltwater pipelines	[] Oil spill evidence	[]		
[] Flowing holes	[·] Saltwater evidence	[]; Surface flow	; seepage	
[] Abandoned wells []; Potential poll. Prob; currently producing	[] Saltwater pipelines	[]; Seepage visible Yes/No	o, tested for leaks Yes/No	
[] TA wells []; Potential poll. Prob; currently producing	[] Flowing holes	[]		
[] SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well psi SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi psi SWD/ER Injection well psi SWD/ER Injection psi SWD/ER Injection well psi SWD/ER Injection well psi SWD/ER Injection psi	[] Abandoned wells	[]		
[] SWD/ER Injection well []; Permit # Pressure-actual psi, Authorized psi Pressure-actual psi, Autho	[] TA wells	[]; Potential poll. Prob.	; currently producing	
[] Gauge connections []: tubing ; T/C annulus ; C/SP annulus [] Gauge connections []: tubing ; T/C annulus ; C/SP annulus [] Gauge connections []: tubing ; T/C annulus ; C/SP annulus [] Gauge connections []: tubing ; T/C annulus ; C/SP annulus [] Gauge connections []: tubing ; T/C annulus ; C/SP annulus [] C/SP annul	[] SWD/ER Injection well [] SWD/ER Injection well	[]; Permit # Pr	ressure-actual psi, Authorized psi, Authorized	psi psi
[] Gauge connections []: tubing	[] Monitoring records			
Well number & GPS coordinates:	[] Gauge connections [] Gauge connections [] Gauge connections	[]: tubing; T/C []: tubing; T/C []: tubing; T/C	annulus ; C/SP annulus annulus ; C/SP annulus ; C/SP annulus annulus ; C/SP annulus .	
	Lease cleanliness: Very good	satisfactory poor	very bad	·
	Well number & GPS coordinates:			
		egis (17) (20) det anno 1885		
				1 T T T T T T T T T T T T T T T T T T T