

KANSAS  
STATE CORPORATION COMMISSION

RECEIVED  
STATE CORPORATION COMMISSION  
8-25-61  
AUG 25 1961  
CONSERVATION DIVISION  
WICHITA, KANSAS

CONSERVATION DIVISION AGENT'S REPORT

TO:  
Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: \_\_\_\_\_ Rooks \_\_\_\_\_  
Location: SE SE NE \_\_\_\_\_ Sec. 16 \_\_\_\_\_ Twp. 10 \_\_\_\_\_ Rge. \_\_\_\_\_ (E) \_\_\_\_\_ (W) 16  
Name of Field: \_\_\_\_\_ Total Depth: 3650

I have this date completed supervision of plugging of:

Lease Name: Conger \_\_\_\_\_ Well No. B-1 \_\_\_\_\_

Operator's Full Name: White & Ellis \_\_\_\_\_

Complete Address: Box 448 El Dorado, Kansas \_\_\_\_\_

Plugging Contractor: same \_\_\_\_\_

Address: \_\_\_\_\_ License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A

Other well as hereafter indicated: \_\_\_\_\_

Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 10AM \_\_\_\_\_ Day 22 \_\_\_\_\_ Month 8 \_\_\_\_\_ Year 61

The above well was plugged as follows:

8 5/8" 242' circulated with cement.

Circulated hole with heavy mud, set cementing plug at 600', displaced  
15 sax cement through drill pipe, heavy mud to 235', set plug, 1/4 sack  
hulls and 15 sax cement, heavy mud to 40', set plug, 1/2 sack hulls and  
filled to bottom cellar with cement.

Signed: Edson Petty  
Conservation Division Agent

Reviewed: Harold Hollis  
Field Supervisor

Remarks:

INVOICED  
DATE 8/31/61  
INV. NO. 3681-W