TO: API Well Number: 15-053-20218-00-00 STATE CORPORATION COMMISSION Spot: SWSWNE Sec/Twnshp/Rge: 33-15S-8W **CONSERVATION DIVISION - PLUGGING** 2998 feet from S Section Line, 2391 feet from E Section Line 130 SOUTH MARKET, SUITE 2078 Lease Name: MARGARET MUNCIE Well #: 1 **WICHITA, KANSAS 67202** County: ELLSWORTH Total Vertical Depth: 2995 feet String Size Depth (ft) Pulled (ft) Comment Operator License No.: 101 KCC Fee Fun 1 SURF 8.625 210 Op Name: KANSAS CORPORATION COMMISSION T1 2.5 2600 Address: 130 S MARKET RM 2078 WICHITA, KS 67202 Well Type: GAS **UIC Docket No:** Date/Time to Plug: 06/18/2009 9:00 AM Plug Co. License No.: 31925 Plug Co. Name: QUALITY WELL SERVICE, INC. Company: QUALITY WELL SERVICE Phone: (620) 727-3410 Proposal Rcvd. from: RICHARD MCINTRYE Proposed SEE BELOW Plugging Method: WitnessType: COMPLETE (100%) Plugging Proposal Received By: JEFF KLOCK Date/Time Plugging Completed: 06/18/2009 3:00 PM KCC Agent: VIRGIL CLOTHIER Perfs: **Actual Plugging Report:** MIRU ON 6-17-2009. ENCOUNTERED OBSTRUCTION AT 470'. PUMPED THRU WITH TANK TRUCK. WELL WENT ON VACUUM. TAG BOTTOM AT 2440'. PUMP 35 SX'S CEMENT WITH 100#'S COTTON HULLS. LET SET OVERNIGHT AND TAGGED CEMENT TOP ON 6-18-2009 AT 1900'. PERFORATE AT 901' AND PUMP 20 SX'S CEMENT WITH CALCIUM CHROLIDE. LET SET FOR ALMOST 2 HRS AND TAGGED CEMENT TOP AT 730'. PERFORATE AT 600' AND PUMP 20 SX'S CEMENT WITH CALCIUM CHLROIDE. LET SET FOR APPROX 1.5 HRS. PERFORATE AT 260' AND «ANSAS CORPORATION COMMISSION CIRCULATE 120 SX'S CEMENT TO SURFACE. USED 195 SX'S CEMENT TOTAL. NOTE: THE 2 1/2 TUBING WAS FOUND ORANGE PEELED TO THE 8 5/8" SURFACE. A WINDOW WAS CUT IN THE 8 5/8" & QUALITY WAS ABLE TO GET DOWN BACKSIDE 400'. OUALITY WAS ABLE TO GET PAST ROUGH SPOT INSIDE TUBING

CIRCULATE 120 SX'S CEMENT TO SURFACE. USED 195 SX'S CEMENT TOTAL. NOTE: THE 2 1/2 TUBING WAS FOUND ORANGE PEELED TO THE 8 5/8" SURFACE. A WINDOW WAS CUT IN THE 8 5/8" & QUALITY WAS ABLE TO GET DOWN BACKSIDE 400'. QUALITY WAS ABLE TO GET PAST ROUGH SPOT INSIDE TUBING AT 470' AND GET DOWN TO 2440'. A SLIM PERFORATING GUN WAS USED TO PERFORATE THE TUBING, THAT WAS USED AS THE PRODUCTION STRING. NO OTHER CASING WAS IN THE HOLE.

RECEIVED

CONTROL #: 20090075001 (Per Abandoned)

Remarks: 60-40 POZ, 4% GEL. LOG TECH TI

60-40 POZ, 4% GEL. LOG TECH TICKET #27798. QUALITY TICKET #2317.

Plugged through: TBG

District: 02

Signed <u>Ungel Clothice</u> (TECHNICIAN)

Form CP-2/3

1