

KCC OIL/GAS REGULATORY OFFICES

Date: 06/30/09

District: 01

Case #: _____

- New Situation
 Response to Request
 Follow-Up

- Lease Inspection
 Complaint
 Field Report

Operator License No: 4058

API Well Number: 15-135-24.922-00-00

Op Name: American Warrior

Spot: SE-NE-NE-NW Sec 33 Twp 19 S Rng 21 E / W

Address 1: P.O. Box 399

335 Feet from N / S Line of Section

Address 2: _____

2633 Feet from E / W Line of Section

City: Garden City

GPS: Lat: 38.36309 Long: 99.64947 Date: 6/30/09

State: Kansas Zip Code: 67846 -0399

Lease Name: Rein SJ Well #: 1

Operator Phone #: (620) 587-3224

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @ 227W/160sxs cement
TD @ 4479'
5-1/2" @ 4474'W/145sxs cement
Port Collar @ 1506' cemented with 140sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

KANSAS CORPORATION COMMISSION

JUL 16 2009
RECEIVED

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alt.II requirements have been met

RECEIVED

JUL 10 2009

KCC DODGE CITY

Verification Sources:

Photos Taken: _____

- | | | |
|---------------------------------------|--|-------------------------------------|
| <input type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: _____ | | |

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 06/30/09

District: 01

License #: 4058

Op Name: 4058

Spot: SE-NE-NE-NW Sec 33 Twp 19 S Rng 21 E W

County: Ness

Lease Name: Rein SJ Well #: 1

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24,922-00-00	335FNL 2633FWL	SE-NE-NE-NW	38.36309-99.64947	1	New well, Alt. II completed

Retain 1 Copy District Office
Send 1 Copy to Conservation Division