KCC OIL/GAS REGULATORY OFFICES

Date: <u>07/01/09</u>	District: 01	Case #:			
	New Situation	Lease Inspection Complaint			
	Response to Request				
	Follow-Up	Field Rep	ort		
Onemater Lieunes No. 4059	API Well Number: <u>15-13</u>	25.24.907.00.00			
Operator License No: <u>4058</u> Op Name: <u>American Warrior</u>			S Rng 26 E / W		
Address 1: P.O. Box 399	335		N / ✓ S Line of Section		
Address 2:	2296		E/W Line of Section		
City: Garden City	GPS: Lat: 38.46592				
State: Kansas Zip Code: 67846 -0399	Lease Name: Keith B		4		
Operator Phone #: (620) 587-3224	County: Ness				
Reason for Investigation:	· · · · · · · · · · · · · · · · · · ·				
Witness Alt.II					
Problem:					
None, cement circulated to surface					
, , , , , , , , , , , , , , , , , , , ,	i.				
Persons Contacted:		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Tersons Contacted.					
•					
Findings:	· · · · · · · · · · · · · · · · · · ·				
8-5/8" @ 222W/150sxs cement	f				
TD @ 4500'					
5-1/2" @ 4489'W/130sxs cement					
Port Collar @ 1785' cemented with 150sxs-si	md-1/4# flo seal-2%cc-	15sxs went to pit	KANCAC CORROBATION COMMON		
			KANSAS CORPORATION COMMISS OF		
·			JUL 1 6 2009		
	(
			RECEIVED		
Action/Recommendations: Follow	v Up Required Yes N	o 🗗 Date:			
Alt.II requirements have been met	v op kedanea	<u> </u>			
RECEIVED (•		
JUL - 9 2009	· •	•			
	,				
KCC DODGE CITY					
Verification Sources:	·		Photos Taken:		
	TA Program	haol Major			
	Courthouse By: IVIIC	hael Maier	<u> </u>		
Other:					
Retain 1 Copy District Office Send 1 Copy to Conservation Division	4		00/00/000		

Form: <u>02/22/2008</u>

Date: 07/01/09			District	: <u>U1</u>		Li	icense #: <u>4058</u>			
Op Name: 4058			Spot: <u>Sf</u>	E-SE-S	W	Sec <u>23</u> Twp <u>1</u>	8 S Rng <u>26</u>	E √ w		
County: Ness		<u> </u>	Lease Na	me: Keith B Well #: 1-23						
I.D. Sign Yes	No		E	Gas V	Venting [Yes No		*		
Tank Battery Condition Condition: Good Questionable Overflowing					Pits Fluid Depth:ft; Approx. Size:ft. xft.					
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N						
Oil Spill Evidence					Flowing Holes					
Abandoned Well	Potential Poll	ution Problem [Yes No 15	П	`A Wells					
				Monitoring Records						
Lease Cleanliness Very Good Satisfactory Poor Very Bad										
SWD/ER Injection Well	Yes	No	Ness 🖭	Gaug	e Connect	ions Yes No)			
Permit #: psi; Authorized: psi					Tubing:; T/C Annulus:; C/SP Annulus:					
Permit #: Pressure – Actual: psi; Authorized: psi					ng:	; T/C Annulus: _	; C/SP Ann	nulus:		
Permit #: 43 (A. C.					Tubing:; T/C Annulus:; C/SP Annulus:					
Permit #: Pressure – Actual: psi; Authorized: psi					ng:	; T/C Annulus: _	; C/SP Ann	nulus:		
API		Spot					Well			
API Number	Footages	Location	GPS		Well #		Status			
15-135-24,907-00-00	335FSL 2296FWL	SE-SE-SW	38.46592-100.16483		1-23	New well, Alt.II completed				
·			ļ, 	<u> </u>			11 27075			
						<u>Uaviadae</u>				
						PRING 9 - JULY				
						V. Commercial Commerci	الرون و000 الما			
						S. D. ⊕ Najtro _m	<u></u>			
						,				

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>