KCC OIL/GAS REGULATORY OFFICE

Date 7/28/09	<u></u>		(2) New Situation () Response to Request
Operator license #3_	3523		() Follow-up
Operator <u>OKT</u>	Resources LCC	·	
Address <u>1900 E</u> 1	5th Bldg 600	Location	<i>3E</i> ,Sec <u>/5</u> ,T <u>/9</u> S,R <u>3/</u> W
Edmone	4,0k 13013	Lease_Harkna	Well # /-/5
	4		Doctf
	405 285-1140		15-171-20722-000
Reason for Investigation	n: Alterna-	ke II Cementin	ig (Rotory)
Problem:			•
· .			
Person(s) Contacted:			
Findings:		· · · · · · · · · · · · · · · · · · ·	·
	4/2 050 50	of % 4654"	TD 4719.
DV T/C	•	, -	575 5x 60/40 Pa 82ge
•			150 sx to the pit
Thru Ul	1 1001, Fall Re	rurns. Circ	1305x to the pit
			KANSAS CORPORATION COMMISSION
		pho	otos taken: AUG 1 4 2009
Action/Recommendation	is: Aft	Camplele	RECEIVED
	RECEIVED ^		
	AUG - 6 2009	ν	
)Lease Inspection)Complaint	111	By <u>Ken</u>	Jehl, k
Field Report	KCC DODGE CITY	PIR	211
etain 1 copy Joint Distric and one copy Conservation		() RBDMS () KGS	() TA program () T-1 database
The one copy comorrant	1 2 0 2 V 3 3 i	() District f	· · · · · · · · · · · · · · · · · · ·

LEASE INSPECTION

YES []I.D. Sign	NONE COMMENTS []			
[] Tank Battery	[]; Condition: good [] questionable [] overflowing []			
[] Pits, tank battery	[]; Fluid depth ft.; approx. size ft x ft			
[] Pit, injection site	[]; Fluid depth ft.; approx. size ft x ft			
[] Gas venting				
[] Oil spill evidence				
[] Saltwater evidence	[]; Surface flow; seepage			
[] Saltwater pipelines	[]; Seepage visible Yes/No; tested for leaks Yes/No			
[] Flowing holes				
[] Abandoned wells				
[] TA wells	[]; Potential poll. Prob; currently producing			
SWD/ER Injection well SWD/ER Injection well SWD/ER Injection well SWD/ER Injection well	[]; Permit #Pressure-actualpsi, Authorizedpsi[]; Permit #Pressure-actualpsi, Authorizedpsi[]; Permit #Pressure-actualpsi, Authorizedpsi[]; Permit #Pressure-actualpsi, Authorizedpsi			
[] Monitoring records				
[] Gauge connections[] Gauge connections[] Gauge connections[] Gauge connections	[]: tubing; T/C arxiulus; C/SP annulus; tubing; T/C annulus; C/SP annulus; tubing; T/C annulus; C/SP annulus; tubing; T/C annulus; C/SP annulus;			
Lease cleanliness: Very good	satisfactorypoorvery bad			
Well number & GPS coordinates:		_		
/				
		1		
		THE PERSON NAMED IN		

•		And the second second second second		
		Table Street, and the party		
		The same of the same of		