Date: <u>08/03/09</u>	District: 01	Case #:				
	New Situation	Lease Inspection				
	Response to Request	Complaint				
	Follow-Up	Field Report				
Operator License No: 4058	API Well Number: <u>15-0</u>	83-21,602-00-00				
Op Name: American Warrior	Spot: NE-NE-SW-SW Sec 23 Twp 21 S Rng 25 E / W					
Address 1: P.O. Box 399	1140	Feet from N/ S Line of Section				
Address 2: P.O. Box 783188	1240	Feet from E / W Line of Section				
City: Garden City	GPS: Lat: <u>38.20658</u>	Long: <u>100.04154</u> Date: <u>8/3/09</u>				
State: Kansas Zip Code: 67846 -0399	Lease Name: <u>Cure</u>	Well #: <u>1-23</u>				
Operator Phone #: <u>(620) 587-3224</u>	County: Hodgeman					
Reason for Investigation:						
Witness Alt.II						
Problem:						
None, cement circulated to surface		KANSAS CORPORATION COMMISSION				
·		AUG 14 2009				
Persons Contacted:		AUS 1 4 2009				
Tersons Contacted:		RECEIVED				
		-16				
Findings:						
8-5/8" @ 221W/160sxs cement						
TD @ 4590'						
5-1/2" @ 4589'W/125sxs cement	1.444.6	and the same of th				
Port Collar @ 1657' cemented with 140sxs-s	md-1/4# flo seal-2%co	c-15sxs went to pit				
Action/Recommendations: Follow	w Up Required Yes	No 🕫 Date: 7/14/09				
Alt.II requirements have been met		LANGE TO THE PARTY OF THE PARTY				
RECEIVED ()						
AUG 1 2 2009						

TA Program

Courthouse

By: Michael Maier

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Verification Sources:

RBDMS

Other:

T-I Database

KCC DODGE CITY

KGS

✓ District Files

Form: <u>02/22/2008</u>

Photos Taken: ___



Date: <u>08/03/09</u> Distri				t: <u>01</u> License #: <u>4058</u>				
Op Name: <u>4058</u> Spot:			Spot: <u>N</u>	NE-NE-SW-SW Sec 23 Twp 21 S Rng 25 E ✓ W				
County: Hodgeman Lease I			lame: <u>Cure</u> Well #: <u>1-23</u>					
I.D. Sign Yes	No		[3]	Gas \	enting	Yes No		3
Tank Battery Condition Condition: Good Questionable Overflowing				Pits Fluid Depth:ft; Approx. Size:ft. xft.				
Pits, Injection Site					ıltwater Pi	nelines		<u></u>
Fluid Depth:	_ft; Approx. S	Size:ft	. xft.	$\boldsymbol{\vdash}$: Y N	Tested for Leaks:	Y N
Oil Spill Evidence				Flowing Holes				
Abandoned Well	Potential Poll	ution Problem	Yes No 🖸	Т	A Wells			
				Monitoring Records				
Lease Cleanliness Very Good S	atisfactory	Poor Very	y Bad					
SWD/ER Injection Well Yes No Hodgeman			Gauge Connections Yes No					
Permit #: psi; Authorized: psi				Tubing:; T/C Annulus:; C/SP Annulus:				
Permit #: P							; C/SP Annulu	
Permit #: Pr			thorized: psi				; C/SP Annulu	
Permit #: Pr	ressure – Actu	al: psi; Aut	thorized: psi	Tubii	ng:	; T/C Annulus:	; C/SP Annulu	is:
API Number	Footages	Spot Location	GPS		Well #		Well Status	
15-083-21,602-00-00	1140FSL 5-083-21,602-00-00 1240FWL NE-NE-SW-SW 38.20658-10		38.20658-100.	04154	1-23	New well, Alt.II completed		
		<u> </u>	<u> </u>		L			