

# KCC OIL/GAS REGULATORY OFFICES

Date: 08/06/09

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5144  
Op Name: Mull Drilling Company, Inc.  
Address 1: 1700 N Waterfront Pkwy  
Address 2: Bldg. 12000  
City: Wichita  
State: Kansas Zip Code: 67206 -6637  
Operator Phone #: (316) 264-6365

API Well Number: 15-135-24939-00-00  
Spot: NE-NW-NW-SE Sec 32 Twp 16 S Rng 23  E /  W  
2589 Feet from  N /  S Line of Section  
2185 Feet from  E /  W Line of Section  
GPS: Lat: 38.61731 Long: 99.88934 Date: 8/6/09  
Lease Name: Mishler-Benson Unit Well #: 1-32  
County: Ness

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None, cement circulated to surface

**Persons Contacted:**

**Findings:**

8-5/8" @ 221 W/150sxs cement  
TD @ 4602'  
5-1/2" @ 4598' W/145sxs cement  
Port Collar @ 1824' cement with 175sxs-smd-1/4# flo seal-2%cc-20sxs went to pit

RECEIVED  
AUG 19 2009  
KCC WICHITA

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met.

RECEIVED  
AUG 13 2009

KCC DODGE CITY

**Verification Sources:**

Photos Taken: \_\_\_\_\_

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 08/06/09

District: 01

License #: 5144

Op Name: 5144

Spot: NE-NW-NW-SE Sec 32 Twp 16 S Rng 23 E W

County: Ness

Lease Name: Mishler-Benson Unit Well #: 1-32

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.939-00-00	2589FSL 2185FEL	NE-NW--NW-SE	38.61731-99.88934	1-32	New well, Alt. II completed