

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission  
Conservation Division  
800 Bitting Building  
Wichita, Kansas

FILE NO. \_\_\_\_\_

LOCATION NW SE SW

SEC. 1 TWP. 10 RGE. 20 W

Dry Hole X Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have today completed supervision of plugging of:

Well No. A-2 Lease \_\_\_\_\_ Sutor \_\_\_\_\_

Operator Champlin Refg Co Address Ellinwood, Kans

Field \_\_\_\_\_ County Rooks

Total Depth 5925 Feet.

(Describe briefly the manner in which the well was plugged)

8 5/8" at 159' circulated with cement.

Circulated hole with heavy rotary mud - pushed cementing plug to 150', displaced 15 sax cement through drill pipe - heavy mud to 55' - set cementing plug and 10 sax cement through drill pipe to bottom cellar.

Cementing by Halliburton Co

**PLUGGING**  
FILE SA 11-24-51 R 200  
BOOK 11-24-51 p 3

**RECEIVED**  
11-27-51  
*[Signature]*  
District Conservation Agent  
Date 11-24-51