## DISTRICT CONSERVATION AGENT'S REPORT

TO:

	<b>,</b>
State Corporation Commission	
Conservation Division 211 North Broadway	FILE NO.
Wichita, Kansas	LOCATION NW SW SW
	SEC. 7 TWP. 10 RGE. 20 V
Dry HoleAbandoned Oil WellAbandone	<del></del>
I have this date completed supervision of plugging of the second supervision of the second supervision of plugging of the second supervision of the second supervision of the second supervision of the second supervision supervision of the second supervision sup	of:
C & G Dra Co	· · · · · · · · · · · · · · · · · · ·
Operator C & G Drg Co Address Wi	conta, hans
FieldCounty	ooks
Total Depth Feet.	Makkamangalan and kalandaga gagan dan sa adhirin an dan kanan anggan da aban an an an an ana ana ka
Plugging Contractor	
Plugging Contractor's License No	
Address	
(Describe briefly the manner in which 8 5/8" at 177' circulated with cement.	n the well was plugged)
Circulated hole with heavy mud, set cemen	ating plug at 170',
1/2 sack hulls and 15 sax cement, mud to	40', set cementing
plug, 1/2 sack hulls and 10 sax cement to	bottom cellar.
REC	
STATE CONSERVATION Date	District Conservation Agent
LUGGING GONSERV TON SIVISION Michita, Kensee	

Wichita, Kansas