	API NUMBER	15-133- Ulb 12-00-00
STATE CORPORATION COMMISSION	SE SW NE	Sec/Twp/Rge <u>33-28-21E</u>
Wichita State Office Bldg PLUGGING SECTION	3157 (GPS)	feet from south section line
130 S. Market, Room 2078 Wichita, Kansas 67202	1878 (GPS)	feet from east section line
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Vanleeuwen GPS #02
Operator License # 101	County	Neosho
Operator: State Of Kansas Fee Fund	Well Total Depth	450 (est) feet
Name & Dent/Vanleeuwen Lease Project	Production Pipe:	2 Size Feet 450 (est)
Address	Surface Casing:	6 Size Feet NA
AB oil well Gas Well SN	WD Well/ Input Well	E-04612.15 D & A
Other well as hereinafter indicated:		
Plugging Contractor: Kepley Well Service, LLC		Lic. # 33749
Address: 19245 Ford Road, Chanute, Kansas 6672	20	
Company to plug at: Hour: Da	ay:17	Month: 9 2008
Plugging proposal received from: Mike Kepley		
Company Name:		Phone:
Were: Clean well to TD, perforate, and then pum	p full of cement from	btm to top thru cement string.
		•
· · · · · · · · · · · · · · · · · · ·		
•		
Plugging Proposal	Received by:	Alan M. Dunning
	•	TECHNICIAN
Plugging attended by Agent: All	Part	TECHNICIAN None XXXXXX
Plugging attended by Agent: All Operations Completed: Hour: Da	Part ay: 17	TECHNICIAN None XXXXXX Month: 9 2008
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 360' of the 1" pipe	Part ay: 17 was removed. The w	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 360' of the 1" pipe 150'. A 1" cement string was lowered to 350' and the	Part ay: 17 was removed. The was well filled with cemer	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and at from btm to top thru this
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 150'. A 1" cement string was lowered to 350' and the cement string. A total of 19 sacks of portland cement	Part ay: 17 was removed. The was well filled with cemer	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and of from btm to top thru this ell. The well was cut off below
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 360' of the 1" pipe 150'. A 1" cement string was lowered to 350' and the	Part ay: 17 was removed. The was well filled with cemer t were used to plug we	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and at from btm to top thru this
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 150'. A 1" cement string was lowered to 350' and the cement string. A total of 19 sacks of portland cement	Part ay: 17 was removed. The was well filled with cemer t were used to plug we	Month: 9 2008 ell was then perforated at 250' and at from btm to top thru this ell. The well was cut off below RECEIVED
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 150'. A 1" cement string was lowered to 350' and the cement string. A total of 19 sacks of portland cement	Part ay: 17 was removed. The was well filled with cement were used to plug well knass	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and at from btm to top thru this ell. The well was cut off below RECEIVED S CORPORATION COMMISSION OCT 0 9 2008 ONSERVATION DIVISION
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 150'. A 1" cement string was lowered to 350' and the cement string. A total of 19 sacks of portland cement plow depth and the location restored. Remarks: Control # 20080018-029	Part ay: 17 was removed. The was well filled with cemer t were used to plug we KANSA	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and at from btm to top thru this ell. The well was cut off below RECEIVED S CORPORATION COMMISSION OCT 0 9 2008
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 150'. A 1" cement string was lowered to 350' and the cement string. A total of 19 sacks of portland cement plow depth and the location restored.	Part ay: 17 was removed. The was well filled with cemer t were used to plug we KANSA	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and at from btm to top thru this ell. The well was cut off below RECEIVED S CORPORATION COMMISSION OCT 0 9 2008 ONSERVATION DIVISION
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 150'. A 1" cement string was lowered to 350' and the cement string. A total of 19 sacks of portland cement plow depth and the location restored. Remarks: Control # 20080018-029	Part ay: 17 was removed. The was well filled with cemer t were used to plug we KANSA	TECHNICIAN None XXXXXX Month: 9 2008 ell was then perforated at 250' and at from btm to top thru this ell. The well was cut off below RECEIVED S CORPORATION COMMISSION OCT 0 9 2008 ONSERVATION DIVISION