

# KCC OIL/GAS REGULATORY OFFICES

Date: 09/04/09

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-24,945-00-00

Op Name: American Warrior

Spot: SW-NW-SW-SW Sec 32 Twp 18 S Rng 21  E /  W

Address 1: P.O. Box 399

790 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

113 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.43879 Long: 99.67754 Date: 9/4/09

State: Kansas Zip Code: 67846 -0399

Lease Name: City Of Bazine Well #: 1

Operator Phone #: \_\_\_\_\_

County: Ness

### Reason for Investigation:

Witness Alt.II

### Problem:

None, cement circulated to surface

### Persons Contacted:

### Findings:

8-5/8" @ 266W/165sxs cement  
TD @ 4280'  
5-1/2" @ 4279'W/145sxs cement  
Port Collar @ 1378' cemented with 160sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

RECEIVED  
SEP 14 2009  
KCC WICHITA

### Action/Recommendations:

Follow Up Required  Yes  No

Date: 7/14/09

Alt.II requirements have been met

RECEIVED

SEP - 9 2009

KCC DODGE CITY

### Verification Sources:

- |                                       |  |                                     |
|---------------------------------------|--|-------------------------------------|
| <input type="checkbox"/> RBDMS        | <input type="checkbox"/> KGS                       | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: _____ |  |                                     |

Photos Taken: \_\_\_\_\_

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 09/04/09

District: 01

License #: 4058

Op Name: 4058

Spot: SW-NW-SW-SW Sec 32 Twp 18 S Rng 21  E  W

County: Ness

Lease Name: City Of Bazine Well #: 1

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.945-00-00	790FSL 113FWL	SW-NW-SW-SW	38.43879-99.67554	1	New well, Alt. II completed