KCC OIL/GAS REGULATORY OFFICES

Date: <u>08/24/09</u>	District:	01	Case #:	
	New	Situation	Lease Inspection	
	Resp	onse to Request	Complaint	
•	Follo	w-Up	Field Report	
Operator License No: 5123	API Well N	Number: <u>15-135-24.9</u>	40-00-00	
Op Name: Pintail Petroleum, Ltd.	Spot: SE	-NW-SW-SESec_	32 Twp 19 S Rng 25 E /	7 w
Address 1: 225 N Market Ste. 300	880		Feet from N/ S Line of Sec	ction
Address 2:	2000		Feet from 🔽 E / W Line of Sec	ction
City: Wichita	GPS: Lat:	38.42327 Long:	100.07005 Date: 8/24/09	
State: Kansas Zip Code: 67202 -2024	Lease Nam	e: Schlegel "DY"	Well #: <u>2-3</u>	
Operator Phone #: (316) 263-2243	County: 1	less		
Reason for Investigation:				
Witness Alt.II				
Problem:	- 4			
None cement circulated to surface				
Persons Contacted:				
Findings:				
8-5/8" @ 208'W/150sxs cement TD @ 4440' 5-1/2" @ 4432'W/200sxs cement				
Port Collar @ 1700' cemented with 150sxs-sn	nd-1/4# flo	seal-2%cc-15sxs	to pit RECEIVED	
			to pit RECEIVED SEP 1 4 2009	·
			KCC WICHITA	
Action/Recommendations: Follow	Up Required	Yes No	Date:	
Alt.II requirements have been met				
RECEIVED SEP - 9 2009				
Verification Sources:			Photos Taken:	
RBDMS KGS T	A Program ourthouse	By: <u>Michael Ma</u>	aier	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: 08/24/09		_	District:	01	_	Lice	nse #: <u>5123</u>			
Op Name: 5123 Spot:				-NW-S	W-SE_	Sec <u>32</u> Twp <u>19</u>	S Rng <u>25</u>]E [√]W		
					Name: Schlegel "DY" Well #: 2-3					
I.D. Sign Yes No				Gas Venting Yes No						
Tank Battery Condition Condition: Good Questionable Overflowing				Pits Fluid Depth:ft; Approx. Size:ft. xft.						
Pits, Injection Site Fluid Depth:	_ft; Approx. S	lize:f0	. xft.	\mathbf{H}	twater Pi ks Visible		ested for Leaks:	1 Y N		
Oil Spill Evidence				Flo	wing Hol	ies				
Abandoned Well	Potential Polle	ution Problem	Yes No 🗠	TA	A Wells					
					Monitoring Records					
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad							
SWD/ER Injection Well			Ness 🖸	Gauge	Connecti	ions Yes No		<u> </u>		
Permit #: Pr						; T/C Annulus:				
Permit #: Pi						; T/C Annulus:				
Permit #:Pi						; T/C Annulus: ; T/C Annulus:				
Permit #:Pi	ressure – Actu	ai: psi; Au	tnorized: psi	1 ubin	g	; 1/C Annulus	, C/SI Alliun	us		
API Number	Footages	Spot Location	GPS		Well #		Well Status			
15-135-24,940-00-00	880FSL 2000FEL	SE-NW-SW-SE	38.42327-100.0	7005	2-3	New well, Alt.II con	npleted			