KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/01/09</u>	District: _)1	Case #:
	New	Situation	Lease Inspection
	Resp	onse to Request	Complaint
•	Follo	w-Up	Field Report
Operator License No: 31783	API Well N	umber: <u>15-10</u>	01-22,185-00-00
Op Name: Mid-Continent Energy Operating Co.	Spot: NE	SW-SE-SW	Sec 21 Twp 19 S Rng 27 E /
Address 1: 100W 5th St. Ste 450	625		Feet from N/ S Line of Section
Address 2: P.O. Box 783188	1940		Feet from E/VW Line of Sectio
City: Tulsa	GPS: Lat:	38.38060	Long: <u>100.31189</u> Date: <u>9/1/09</u>
State: Ok. Zip Code: 74103 -4254	Lease Nam	e: <u>Shauf</u>	Well #: 1-21
Operator Phone #: (918) 587-6363	County: 1	ane	
Reason for Investigation:			
Witness Alt.II			
Problem:	•		
None cement circulated to surface.			
Persons Contacted:			
Findings			
Findings: 8-5/8" @ 302'W/			
TD. @ 4700'			
4-1/2 @ 4682'W/300sxs			
Port Collar @ 2112W/ 215sxs-smd-1/4# flo se	eal-2%cc-2	0sxs to pit	
			RECEIVED
			SEP 14 2009
			RCC WICHITA
Action/Recommendations: Follow	Un Dagwined	□Vas □Na	
Alt.II requirements have been met.	Up Required	Yes No	Date: <u>7/14/09</u>
·			
RECEIVED			
SEP - 9 2009			
KCC DODGE CITY		 	
Verification Sources:			Photos Taken:
RBDMS KGS T	A Program	n 14' '	and Main
	ourthouse	By: Mich	nael Maier
Other:			

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>



Date: 09/01/09		_	District:	01	<u></u>	License #: 31783	_
Op Name: 31783			Spot: NE	Spot: NE-SW-SE-SW		Sec <u>21</u> Twp <u>19</u> S Rng <u>27</u> E [/] W	
County: Lane			Lease Na	ne: <u>Shauf</u>		Well #: <u>1-21</u>	_
I.D. Sign Yes	No		•	Gas Ve	nting _	Yes No	
Tank Battery Condi		le Overflow	ing 🖸	Pits		ft; Approx. Size:ft. xft.	
Pits, Injection Site Fluid Depth:	_ft; Approx. S	ize:ft.	. xft.	$oldsymbol{\sqcup}$	twater Pi	ipelines E: Y N Tested for Leaks: Y N	.
Oil Spill Evidence				Flo	wing Hole	les	
Abandoned Well	Potential Pollu	ution Problem	Yes No		Wells		
Lease Cleanliness				Mo	nitoring l	Records	
Very Good S	atisfactory	Poor Very	y Bad				
SWD/ER Injection Well			Lane 🖸			tions Yes No	
Permit #: Pr						; T/C Annulus:; C/SP Annulus:	
Permit #:Pi						; T/C Annulus:; C/SP Annulus:	
Permit #:P						; T/C Annulus:; C/SP Annulus:	
Permit #: Pi	ressure – Actu	al: psi; Au	thorized: psi	1 ubing	g:	; T/C Annulus:; C/SP Annulus:	=:
API Number	Footages	Spot Location	GPS		Well #	Well Status	
15-101-22,185-00-00	625FSL 1940FWL	NE-SW-SE-SW	38.38060-100.3	1189	1-21	New well, Alt.II completed	
							_
			1				