## KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/22/09</u>	District: _	01	Case	#:
	New	Situation	Lease Ins	pection
	Resp	onse to Request	Complain	nt
	Follo	w-Up	Field Rep	oort
Operator License No: 4058	API Well N	Number: <u>15-083-2</u>	1,604-00-00	
Op Name: American Warrior	Spot: <u>NV</u>	<u>/-SE-SE-SW</u> s	ec <u>23                                    </u>	_S Rng <u>25</u> E / \sqrt{W}
Address 1: P.O. Box 399	335		Feet from	N / S Line of Section
Address 2:				<b>V</b> E / W Line of Section
City: Garden City				Date: <u>9/22/09</u>
State: <u>Kansas</u> Zip Code: <u>67846 -0399</u>				Well #: <u>2-23</u>
Operator Phone #:	County: 1	lodgeman		
Reason for Investigation:				
Witness Alt.II				
Problem:				
None, cement circulated to surface				
Persons Contacted:	<del></del>			
Findings:		<del></del>		
8-5/8" @ 222W/160sxs cement				
TD @ 4532'				
5-1/2" @ 4531'W/125sxs cement				RECEIVED
Port Collar @ 1614' cemented with 130sxs-sn	nd-1/4# flo	seal-2%cc-15s	xs went to pit	
·				OCT 0 5 2009
				KCC WICHITA
				NOC WICHITA
	· <del>· · · · · · · · · · · · · · · · · · </del>			
Action/Recommendations: Follow	Up Required	Yes No	Date: Z	/14/09
Alt.II requirements have been met				,
RECEIVED (				
SEP 3 0 2009				
Verification SouKCC DODGE CITY				Photos Taken:
	4 B			I notos l'aken;
	A Program ourthouse	By: Michael	Maier	
Other:	out tilouse			

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>09/22/09</u>		_	District:	01	_	License #: 4058			
Op Name: 4058		,	Spot: <u>N</u> \	N-SE-S	E-SW	Sec <u>23</u> Twp <u>21</u> S Rng <u>25</u> E 📝 W			
County: Hodgeman	·····		Lease Na	me: <u>Cu</u>	re	Well #: 2-23			
I.D. Sign Yes	No		N	Gas V	enting [	Yes No			
Tank Battery Condition  Condition: Good Questionable Overflowing				Pits Fluid Depth:ft; Approx. Size:ft. xft.					
Pits, Injection Site	_ft; Approx. S	Size:ft	. xft.	<b>  </b>	ltwater Pi	ipelines  e: Y N Tested for Leaks: Y N			
Oil Spill Evidence				FI	owing Hol	les			
Abandoned Well	Potential Poll	ution Problem	Yes No 🖺	Т	A Wells				
Lease Cleanliness			10	М	onitoring	Records			
Very Good S	atisfactory	Poor Very	y Bad						
SWD/ER Injection Well		-	Hodgeman 🔯			tions Yes No			
Permit #:Pi						; T/C Annulus:; C/SP Annulus:; ; T/C Annulus:; C/SP Annulus:			
Permit #: Pr			thorized: psi			; T/C Annulus:; C/SP Annulus:			
Permit #: P		<del></del>	thorized: psi			; T/C Annulus:; C/SP Annulus:			
retinit #1	ressure - Actu	ai psi, Au	ps.		.в	, 1.01			
API Number	Footages	Spot Location	GPS		Well #	Well Status			
15-083-21,604-00-00	335FSL 2299FEL	NW-SE-SE-SW	38.20438-100.0	3783	2-23	New well, Alt.II completed			