

KCC OIL/GAS REGULATORY OFFICE

Date 9/30/09

- New Situation
- Response to Request
- Follow-up

Operator license # 3842

API # 15-101-22194-00-00

Operator Larson Engineering, Inc. dba  
Larson Operating Company

Address 562 W. State Rd. 4

Location SE-SE-NE, Sec 8, T 19 S, R 29 W

Olmitz, KS 67564-8561

Lease Rita Well # 2-8

County Lane

Operator phone number 620-653-7368

Reason for Investigation: Company requested a witness to the Alternate II cementing job.

Problem: Alternate II cementing requirements have not been met.

Person(s) Contacted: \_\_\_\_\_

Findings: 8 7/8" set @ 261' @ 175 sx cmt. 4 1/2" set @ 4646' @ 275 sx cmt. on primary  
cementing job. Company opened port collar @ 2115'. Swift Services Inc. pumped  
250 sx SMD, circulating 20 sx to the pit. Closed port collar.

RECEIVED

OCT 08 2009

KCC WICHITA

GPS-38.41837°N, 100.54115°W photos taken: \_\_\_\_\_

Action/Recommendations: None. Alternate II cementing requirements have been met.

RECEIVED

OCT - 2 2009

KCC DODGE CITY

- Lease Inspection
- Complaint
- Field Report

By Eric M. [Signature]

Retain 1 copy Joint District Office  
Send one copy Conservation Division

- RBDMS
- KGS
- District files
- TA program
- T-1 database
- Courthouse

[Signature]

