KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/14/09</u>	District: 01	Case #:
	New Situation	Lease Inspection
	Response to Reques	t Complaint
·	Follow-Up	Field Report
	·	22184 aB
Operator License No: <u>5144</u>	API Well Number: 15-	
Op Name: Mull Drilling Company, Inc.		
Address 1: 1700 N Waterfront Pkwy	2150	
Address 2: Bldg. 12000		Feet from Feet from Via Line of Section
City: Wichita		Long: 100.42172 Date: 9/14/09
State: Kansas Zip Code: 67206 -6637		Well #: <u>1-33</u>
Operator Phone #: <u>(316) 264-6365</u>	County: Lane	
Reason for Investigation:		
Witness Alt.II		
Problem:	and the second s	
None, cement circulated to surface		
Persons Contacted:		
Findings:		
8-5/8" @ 223' W/150sxs cement TD @ 4680' 4-1/2" @ 4669' W/200sxs cement Port Collar @ 2174' cement with 230sxs-smd	-1/4# flo seal-2%cc-	20sxs went to pit
		CLO
• •		SEP 2 1 2000
		SEP 2 1 2009 KCC WICHITA
Action/Recommendations: Follow	Up Required Yes	No Date:
Alt.II requirements have been met.		
RECEIVED (
SEP 1 5 2009		
KCC DODGE CITY Verification Sources:		Photos Taken:
RBDMS KGS 1	`A Program	
	Courthouse By: _N	lichael Maier
Other:		
Retain 1 Copy District Office Send 1 Copy to Conservation Division		B

Form: <u>02/22/2008</u>

Date: 09/14/09		_	District	01		Licer	nse #: <u>5144</u>		
Op Name: 5144 Spot				<u>NW-SW-SW-NE</u> Sec <u>33</u> Twp <u>17</u> S Rng <u>28</u> ☐ E 🕢 W					
County: Lane L				me: <u>R-</u>	R Unit		Well #: 1-33		
I.D. Sign Yes	No		2	Gas V	Venting	Yes No		গ	
Tank Battery Condition Condition: Good Questionable Overflowing			/ing	 -	Pits Fluid Depth:ft; Approx. Size:ft. xft.				
Pits, Injection Site				S	altwater Pi	ipelines		[47] [47]	
Fluid Depth:	_ft; Approx. S	Size:fo	t. xft.					N	
Oil Spill Evidence				F	lowing Hol	les			
Abandoned Well	Potential Poll	ution Problem [Yes No 🕫	1	`A Wells				
				Monitoring Records					
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad					, , .	
SWD/ER Injection Well	Yes _	No	Lane	Gaug	e Connect	ions Yes No		47	
Permit #: P						; T/C Annulus:			
Permit #: Pr						T/C Annulus:			
	ressure – Actu ressure – Actu		thorized: psi			; T/C Annulus:			
Permit #:P	ressure – Actu	ar: psi; Au	thorized: psi	Tubi	ığ	; T/C Annulus:	, C/SF Annulus:		
API Number	Footages	Spot Location	GPS		Well #		Well Status		
15-101-22,184-00-00	2150FNL 2578FEL	NW-SW-SW-NE	38.53371-100.4	2172	1-33	New well, Alt.II com	pleted		
