KCC OIL/GAS REGULATORY OFFICES

Date: 10/06/09	District: _0	1		Case #	#:	
	New S	Situation	Г	Lease Inst	pection	
	Respo	nse to Request	Ţ	Complain	t	_
	Follov	v-Up	Ì	Field Rep	ort	aβ
		. 45.40	- 04 450	— 	-135-710	953000
Operator License No: 4058						
Op Name: American Warrior	-	-NW-NE-SW				E / VW
Address 1: P.O. Box 399						S Line of Section
Address 2: P.O. Box 783188	1500				لنا ليا	V Line of Section
City: Garden City	_	38.42828				10/6/09
State: Kansas Zip Code: <u>67846 -0399</u>	Lease Name	: Stecker			Well #: <u>2-</u>	6
Operator Phone #: <u>(620) 587-3224</u>	County:	ess	••••			
Reason for Investigation:						
Witness Alt.II						
Problem:						
None, cement circulated to surface						
Persons Contacted:						
Findings:						
8-5/8" @ 224W/150sxs cement	•					
TD @ 4287'						
5-1/2" @ 4286'W/175sxs cement						
Port Collar @ 1387' cemented with 150sxs-s	md-1/4# flc	seal-2%cc-	15sxs we	ent to pit		
0				•		
Action/Recommendations: Follow	w Up Required	Yes No	D 145	Date:		
Alt.II requirements have been met					RE	CEIVED
RECEIVED					UC.	T 1 5 2009
						/ 1 J 2003
OCT 1 3 2009					KCC	WICHITA
Verification Sources:					Dhotos To	ıken:
		İ			1 110105 1 8	
hamad	TA Program	Bv: Mich	hael Maie	r		
	Courthouse	,	المالتا المحسر			
Other:				·		
Retain 1 Copy District Office						

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: 10/06/09		Distri	ct: <u>01</u>		Lice	ense #: <u>4058</u>					
Op Name: 4058 Spot:				-NE-SW	Sec <u>6</u> Twp <u>19</u>	S Rng <u>21</u>	E W				
				ecker		_ Well #: <u>2-6</u>					
I.D. Sign Yes No	<u>က</u>	Gas	Venting [Yes No		[47]					
Tank Battery Condition Condition: Good Questio	nable Overflow	ving	Fluid		ft; Approx. Siz	e:ft. x	ft.				
Pits, Injection Site				Saltwater Pipelines							
Fluid Depth:ft; Appro	x. Size:f	t. xft.	Le	aks Visible	:: Y N	Tested for Leaks:	Ϋ́N				
Oil Spill Evidence			F	lowing Ho	les						
Abandoned Well Potential P	ollution Problem [Yes No 🕫		A Wells							
				lonitoring	Records						
Lease Cleanliness Very Good Satisfactory	Poor Ver	y Bad									
SWD/ER Injection Well Yes	No	Ness 🗈	Gaug	e Connect	ions Yes No		47				
Permit #: Pressure - Ad	ctual: psi; Au	thorized: ps	si Tubi	ng:	; T/C Annulus:	; C/SP Annulus:					
Permit #: Pressure - Ac					; T/C Annulus:						
Permit #: Pressure – Ad					; T/C Annulus:						
Permit #: Pressure – A	ctual: psi; Au	thorized: ps	si lubi	ng:	; T/C Annulus:	; C/SP Annulus:					
API Number Footage	s Spot Location	GPS		Well #	# Well Status						
953 2310FSL 15-135-24 253-00-00 1500FWL N/2-NW-NE-SW 38.42828-		38.42828-99.6	8-99.69075		New well, Alt.II completed		 				
			 								
						•					
			, , , , , , , , , , , , , , , , , , , 								