

15-163-03091-0000

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION CSE

SEC. 22 TWP. 10 RGE. 20W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 7 Lease _____ Sutor Room 306 - Koch Bldg.

Operator Champlin^{Oil} Refg Co Address Wichita, Kans

Field _____ County Rooks

Total Depth 3840 Feet.

Plugging Contractor Sierra Pet Co & Halliburton Cementing

Plugging Contractor's License No. _____

Address _____

(Describe Briefly the manner in which the well was plugged)

8 5/8" at 214' circulated with cement.

Gunned pits, filled hole with heavy mud, pumped cementing plug
to 255', followed by 80 sax cement - cement 255' to 0'.

Cementing by Halliburton Cementing Co.

District Conservation Agent

Date 4-5-57

PLUGGING
FILE SEC 22 T. 10 R. 20W
BOOK PAGE 4 LINE 34

RECEIVED
STATE CORPORATION COMMISSION

APR 8 - 1957 04-08-57

CONSERVATION DIVISION
Wichita, Kansas