

Date 11/5/09

- New Situation
- Response to Request
- Follow-up

Operator license # 3842

15-171-20734-0000

Operator Larson Engr / Larson Operating Co

750 FNL & 330 FEL

Address 562 W. State Rd A

Location N/2 SE NENE, Sec 22, T17 S, R31 W

Olmitz, Ks 67564

Lease Donna Well # 1-22

County Scott

Operator phone number 620 653-7368

Reason for Investigation: Alternate II Cementing API # 15-171-20734

8 7/8" 258 w/ 175sx; 5 1/2" 4648 w/ 200sx

Problem: Port Collar @ 2218'

RECEIVED
KANSAS CORPORATION COMMISSION

NOV 19 2009

Person(s) Contacted: _____

CONSERVATION DIVISION
WICHITA, KS

Findings: Swift Services pumped 190sx 5MID thru port collar @ 2218'. Circulated 20sx to the pit.

Given Permit to Drill Footage = 750 FNL 330 FEL

<u>Leo 7.0</u>	<u>NAD 27 GPS</u>	<u>FSL</u>	<u>FNL</u>	<u>NAD 83 GPS</u>	<u>FSL</u>	<u>FNL</u>
<u>38.56771°N</u>	=	<u>4507 FSL</u>	<u>765 FNL</u>	<u>38.56773°N</u>	=	<u>4508 FSL 764 FNL</u>
<u>100.72453°W</u>	=	<u>309 FEL</u>	<u>309 FEL</u>	<u>100.72495°W</u>	=	<u>308 FEL 308 FEL</u>

Action/Recommendations: _____

Alternate II Cementing Complete

RECEIVED

NOV 17 2009

KCC DODGE CITY

- Lease Inspection
- Complaint
- Field Report

By

Ken Sehtik
PIRTA

Retain 1 copy Joint District Office.
Send one copy Conservation Division

- RBDMS
- KGS
- District files
- TA program
- T-1 database
- Courthouse